

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/GRB21003128/EBS3Q2
Date: 17/08/2021

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SME2368X	Insured Vehicle No :	SLV1952M
Date of Loss:	03/03/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0000953

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SME2368X	Engine No:	F4823063B48B20A
Make & Model:	BMW X3 XDRIVE20I, 2.0 M SPORT HID SR NAV (A)	Chassis No:	WBATR12020LC94389
Reg. Date:	24/09/2018 (Man. Year: 2018)	Odometer:	51460 km
Colour:	Black		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/50 R19	Rear Tyre Size:	245/50 R19
Front Left Side:	Pirelli 4 mm	Rear Left Side:	Pirelli 4 mm
Front Right Side:	Pirelli 4 mm	Rear Right Side:	Pirelli 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	612.40	94.00	518.40	84.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,570.00	4,568.00	1,002.00	17.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	6,182.40	4,662.00	1,520.40	24.59
+ GST 7.00/7.00% (\$\$)	432.77	326.34	106.43	24.59

Nett Amount (S\$)	6,615.17	4,988.34	1,626.83	24.59
+ Car Rental (4.0 x S\$150.00/day + 7.00% GST) (S\$)		642.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,637.79		

INSPECTION

Date of Assignment: 09/03/2021

Date Inspected: 05/04/2021

Estimated Period of Repair: 4.0 days

Inspected At:

Performance Motors Limited (Alexandra)
 303 Alexandra Road, Sime Darby Performance Centre
 Singapore 159941

Adjuster: CHEN TSUE YEE**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Jun 2021)
Parts:	M1-SUV	BMW X3 XDRIVE20I 2.0 M SPORT HID SR NAV (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SME2368X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
2	10		*EXPANDING RIVET BLACK	Necessary	14.00 FS	*14.00 FS
3	1		*RR RH WHEEL ARCH TRIM PRIMED (M)	Not Necessary	282.75 FS	*- FS
4	1		*(S/L) RR RH WHEEL ARCH TRIM PRIMED	Not Necessary	235.65 FS	*- FS
					Total Parts (S\$)	612.40
						94.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO MAKE GOOD REAR BUMPER ,REAR RIGHT FENDER AND REPLACE WHEEL ARCH TRIM	New	2,550.00	1,700.00
2	TO RESPRAY REAR BUMPER ,REAR RIGHT FENDER AND REAR RIGHT WHEEL ARCH TRIM	New	2,666.00	2,532.00
3	TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	168.00
4	TO REMOVE OLD PDC ASSEMBLY ,REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECK FOR PROPER FUNCTION	New	177.00	168.00
Gross Labour Cost (\$)			5,570.00	4,568.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >