



CYCLE & CARRIAGE

AIG-OD CLAIM
SURVEY: 09/03/21
UKK - STEVE

VEHICLE NO : SMK4145C

MODEL : MIT/OUTLANDER 2.0

WIP : 63746

Material	:	\$	<u>2,753.52</u>
Labour	:	\$	<u>2,350.00</u>
Sub-Total	:	\$	<u>5,103.52</u>
Less 2% Disc	:	\$	<u>—</u>
Less Excess	:	\$	<u>600.00</u>
Total	:	\$	<u>4,503.52</u>
GST 7%	:	\$	<u>315.25</u>
Grand Total	:	\$	<u>4,818.77</u>

Re- Finalise By/Date : Larry on 01/04/21

REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 05 WORKING DAYS + 2 days (wk-end)



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Table with 2 main columns: Invoice Name & Address, Owner Name & Vehicle Info. Includes details for AIG Asia Pacific Insurance Pte. Ltd. and Mitsubishi Outlander 2.0 Modern.

Table with 6 columns: Account No, Terms, Date/Time Printed, CSE, Operator, WIP No. Row 1: KAX0008, Credit, 01/04/2021/ 09:04, BLE, 884 / Lauro Songcuan, 63746

Main items table with columns: Description of Goods / Services, Qty, Unit Price, Disc%, Amount. Lists various repair items like RENEW TAILGATE AND REAR BUMPER, SPRAY PAINT REAR BUMPER AND TAILGATE, etc.

This is not an official tax invoice. This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**PRO-FORMA INVOICE**

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 22/03/2021	Cust No/Name	KCV10970/MR Hoe Kah Hui (he Jiahui)
	Reg No/Reg Date	SMK4145C / 09/04/2019
	Date In/Mileage	22/03/2021/ 28826
	Chassis/Package	GF7W0600580 /DC17P
	Engine No	4J11AC1361
	Make/Model	MIT/19MY OUTLANDER 2.0 MODERN(995)
	Colour/Trim	P02 RED METALLIC / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	01/04/2021/ 09:04	BLE	884 / Lauro Songcuan	63746

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X DAM, TAILGATE, LWR ✓	1.00	41.00	23.00	31.57 ✓
X MARK, OUTLANDER ✗	1.00	95.00	23.00	73.15 ?
X DECAL, MIVEC ✓	1.00	36.00	23.00	27.72 ✓
Z TEXT				
OD CLAIM - AIG				
SURVEY: STEVE (LKK) 09.03.2021				
DOA: 08.03.2021				
05 DAYS				

Pro Forma

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	2,753.52			
Labour	2,210.00			
Standard Menu	0.00	7% GST on	4503.52	315.25
Specialist Job	0.00			
Diagnostics Job	0.00			
Sundry/Others	-460.00			
Total(w/o GST)	4,503.52		Total Payable	4,818.77

This is not an official tax invoice.
This is a computer generated document, no signature is required.

CAR NO: SMK4145C

WIP: 63746

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	Make <u>Outlander</u>	? / SUPP			
2		? / SUPP			
3		? / SUPP			
4		? / SUPP			
5		? / SUPP			
6		? / SUPP			
7		? / SUPP			
8		? / SUPP			
9		? / SUPP			
10		? / SUPP			
11		? / SUPP			
12		? / SUPP			
13		? / SUPP			
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

	DATE	TAKEN BY
PHOTO BEFORE PAINT		
PHOTO AFTER PAINT		
PHOTO OF MOUNT TO CELLETTE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBAORD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: OUTLANDER

SURVEYOR: STEVE

Item	Setting	Information
M.U.T.-3 Version		SEW20121-00
V.C.I. Version		B179
Vehicle Information		DBA-GF7W 2019MY

SMK 4145 C.

AM.O.T. III Key .chk.

↳ Read SCC only - Before -

All DTCs

2021.03.26

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition
KOS/IMMO/Keyless	KOS_8A880020		No DTCs	
OSS	OSS_9588000B		No DTCs	
CORNER SENSOR/SONAR	SONAR_9D080000		Non-equipped System or Communication Error	
ACC/FCM	ACCFCM_4B080000		Non-equipped System or Communication Error	
Multi Around Monitor	CAMERA_94080100		Non-equipped System or Communication Error	
EPB	EPB_4C080000		No DTCs	
Gateway	GW_C1000000		Non-equipped System or Communication Error	
FCM/LDW/AHB	ADAS_4B080003		Non-equipped System or Communication Error	
BSW	BSW_RAD_MASTER_A0080000		Non-equipped System or Communication Error	
BSW(SUB)	BSW_RAD_SLAVE_A0080000		Non-equipped System or Communication Error	

Item	Setting	Information
M.U.T.-3 Version		SEW20121-00
V.C.I. Version		B179
Vehicle Information		DBA-GFTW 2019MY

SMK 4145 C.

↳ M.U.T. III Diag. chk.

↳ Read & clear DTC.

After

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition
KOS/IMMO/keyless	KOS_8A880020		No DTCS	
OSS	OSS_9588000B		No DTCS	
CORNER SENSOR/SONAR	SONAR_9D080000		Non-equipped System or Communication Error	
ACC/FCM	ACCSCFM_4B080000		Non-equipped System or Communication Error	
Multi Around Monitor	CAMERA_94080100		Non-equipped System or Communication Error	
EPB	EPB_4C080000		No DTCS	
Gateway	GW_C1000000		Non-equipped System or Communication Error	
FCM/LDW/AHB	ADAS_4B080003		Non-equipped System or Communication Error	
BSW	BSW_RAD_MASTER_A 0080000		Non-equipped System or Communication Error	
BSW(SUB)	BSW_RAD_SLAVE_A0 080000		Non-equipped System or Communication Error	