

SLK683D.

TPA16.

Cecilia.

Hyundai Elantra.

KMHDA81CMH4310789.

- Rees Bumper Deband 459.40 ✓
- Rees Bumper clips. <sup>new</sup> 30(SN) ✓
- Rees Bumper Side Holder <sup>new</sup> x02. 44.3x2=88.60 ✓
- Rees Bumper lower Garnish. <sup>Deband</sup> 250.30. 95.60 ✓
- Rees Bumper Reflector x02. <sup>RH</sup> ~~unband~~ 95.6x2=191.20.
- Rees Bumper Reinforcement. <sup>Dented</sup> 394.80 ✓
- Rees Bumper Reinforcement Bracket x05 <sup>new new</sup> 18x5=90 +
- ~~Rees Bumper Reinforcement Stay x02~~ 200(SN)
- Reverse sensor. <sup>Damaged</sup> 280(SN).
- Rees End Panel. <sup>Dented</sup> 569.40. ✓
- Rees End Panel Top Garnish. <sup>Deband</sup> 189.70 ✓
- Rees End Panel Top Garnish clips. <sup>new</sup> 10(SN) ✓
- Rees End Panel Sealant. <sup>new</sup> 60(SN) ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

SLK 683D.

Bootlid Repairs		1578.10. +
Bootlid Lock	} <sup>2</sup> <sub>not</sub> <sub>rec</sub>	132.50 +
Bootlid Weatherstripe		145.60 +
Hyundai Logo	} <sub>rec</sub>	42.50 ✓
Elantra Wording		48.80 ✓
S Emblem		45.90 ✓

list: 2185  
 less 20%: 1748

S.N: 300

Panel Beating.	<del>1200</del> 600
Spray Painting.	<del>1000</del> 700
Wiring.	<del>50</del> 30
To remove reverse sensor	<del>100</del> 50
To remove upholstery.	<del>150</del> 60
To spray tuft coat.	<del>150</del> 60
To transfer bootlid fittings.	150. X

Total: 3548

A/c: 2.8K . 05 Days.