



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: YU DOMINIC YISHAN			Ref: CS/ASM21003131/Aqf3e2 Date: 30/08/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 5048E	Veh. Inspected	SMU 1375Y	
Policy No.	VFX/P2419138	Coverage (\$)	0.00	
Claim No.	S1M034PD	Excess (\$)	0.00	
Assign From	YU DOMINIC YISHAN	Assign Date	09/03/2021	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ CLA250	c.c	1991	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	WDD1173442N194914	Colour	RED	
Odometer	97086 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/40 R18	CONTINENTAL	6 mm	
L/H Front Tyre	235/40 R18	CONTINENTAL	6 mm	
R/H Rear Tyre	235/40 R18	CONTINENTAL	6 mm	
L/H Rear Tyre	235/40 R18	CONTINENTAL	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND UNDERCARRIAGE. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	06/03/2021	Inspection Date	10/03/2021	
Survey held at	T K MOTOR WORKSHOP BLK 1 KAKI BUKIT AVE 6 #02-56 SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		