



Final Report

Estimate No. : **b1 57713**
Date Estimated : **04/03/2021**
Prepared By : **Han Kwan Yong**

- ESTIMATE REPAIR FOR -
Kim Lin Yen (Jin Ningyuan)
12 Bedok Rise
#03-42

Singapore 465407

- ACCOUNT - 135
China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLM5268B	WBA1V720605G864	31/03/2017	116d	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper, make good bootlid, knock out tail panel, make good tail panel and remove attachments.	2,550.00	0.00	2,550.00
To respray rear bumper, boot lid and tail panel	2,399.00	0.00	2,399.00
To transfer PDC assembly parts and connect to new bumper.	150.00	0.00	150.00
To remove and install boot compartment carpet and garnish to facilitate repair.	231.00	0.00	231.00
To check electrical wiring system and lighting at the rear section.	150.00	0.00	150.00
To supply rear emboss number plate.	83.00	0.00	83.00
Sundries	150.00	0.00	150.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# HOLDER CAMERA SYSTEM	36.50	1.00	0.00	36.50
REAR BUMPER CENTRE GUIDE (M)	56.05	1.00	0.00	56.05
REAR BUMPER PRIMED (RFC)	1,020.10	1.00	0.00	1,020.10
REAR PDC HOLDER SET	25.75	1.00	0.00	25.75
NUMBER PLATE LIGHT LED	24.05	1.00	0.00	24.05
(DG/SL) ADHESIVE SET K6	53.05	1.00	0.00	53.05

#

SUPPLEMENTARY ITEMS

Total Labour :	5,713.00
Total Parts :	1,215.50
Total Labour & Parts :	6,928.50
Deduction for Excess :	
Total Repair Costs less Excess:	6,928.50
GST @7%:	485.00
Grand Total :	7,413.50

CAR RENTAL=\$428.00
GIA SEARCH FEE=\$2.00