



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21003139/T1Uvd3n2	
			Date: 22/09/2021	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	CB 7118C	Veh. Inspected	SKJ 749R
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2100761/RUC	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	09/03/2021
2. Vehicle Particulars & Condition				
	Make & Model	VOLKSWAGEN BEETLE	c.c	1197
	Engine No.	HIDDEN	Year of Reg.	2013
	Chassis No.	WVWZZZ16ZCM655161	Colour	WHITE
	Odometer	-	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/60 R16	MICHELIN	6 mm
	L/H Front Tyre	215/60 R16	MICHELIN	6 mm
	R/H Rear Tyre	215/60 R16	MICHELIN	6 mm
	L/H Rear Tyre	215/60 R16	MICHELIN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	08/03/2021	Inspection Date	11/03/2021
	Survey held at	56 LOYANG WAY # 04-04		
	Repairer	AP AUTOMOTIVE SERVICES PTE LTD		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	