

AP Automotive Services

AP AUTOMOTIVE SERVICES PTE LTD
ROC: 202022890H
BLOCK 9006
TAMPINES STREET 93 #01-202
SINGAPORE 528840
TEL: 6784 4465
FAX: 6787 4886

Estimation

Date
Vehicle SKJ 749 R
Make/Model VOLKSWAGEN BEETLE
Chassis No.

No.	Description	Unit	Unit Price	Amount	
	Parts Replacment				
1	TAILGATE <i>or bt</i>	1	(1388)	\$ 1,588.00	1388
2	TAILGATE WINDSCREEN MOULDING <i>rel</i>	1		\$ 227.00	227
3	TAILGATE CENTER LAMP <i>x n</i>	1		\$ 156.00	
4	TAILGATE LOGO OPENER <i>x n</i>	1		\$ 580.00	
5	TAILGATE EMBLEM - BEETLE <i>rel</i>	1		\$ 136.00	136
6	TAILGATE LOCK <i>x n</i>	1		\$ 186.00	
7	TAILGATE LOCK CATCH <i>x n</i>	1		\$ 90.00	
8	TAILGATE TRIM <i>x n</i>	1		\$ 318.00	
9	TAILGATE HINGE SET <i>x</i>	2		\$ -	
10	TAILGATE DAMPER SET <i>x n</i>	2	124.00	\$ 248.00	
11	TAILGATE WEATHERSTRIP <i>int</i>	1	-	\$ 324.00	324
12	TAIL LAMP L+R <i>LH x n, RH - car</i>	2	270.00	\$ 540.00	270
13	TAIL LAMP LOWER BRACKET L+R <i>x n</i>	2	58.00	\$ 116.00	
14	REAR BUMPER <i>de</i>	1	1386	\$ 1586.00	1386
15	REAR BUMPER NUMBER PLATE LAMP L+R <i>int</i>	2	28.00	\$ 56.00	56
16	REAR BUMPER TOW COVER <i>x n</i>	1		\$ 30.00	
17	REAR BUMPER REVERSE SENSOR SET <i>n</i>	4	223.00	\$ 892.00	650
18	REAR BUMPER REFLECTOR L+R <i>x n</i>	2		\$ -	
19	REAR BUMPER LOWER <i>de</i>	1		\$ 174.00	174
20	REAR BUMPER RETAINER L+R <i>car</i>	2	102.00	\$ 204.00	204
21	REAR BUMPER CENTER BRACKET <i>de</i>	1		\$ 74.00	74
22	REAR BUMPER REINFORCEMENT BAR <i>bt</i>	1		\$ 686.00	686
23	REAR BUMPER LOWER BRACKET L+R <i>x LH, RH - car</i>	2	129.00	\$ 258.00	129
24	REAR BUMPER SPONGE <i>x</i>	1		\$ -	
25	REAR FENDER L+R <i>x</i>	2		\$ -	
26	REAR FENDER AIR VENT L+R <i>x</i>	2		\$ -	
27	REAR FENDER INNER TRIM L+R <i>x LH, RH - car</i>	2	748.00	\$ 1,496.00	748
28	REAR FENDER COWLING L+R <i>x LH, RH - car</i>	2	236.00	\$ 472.00	236
29	END PANEL <i>bt</i>	1	(932)	\$ 1,032.00	932
30	END PANEL AIR VENT <i>x n</i>	1		\$ -	
31	END PANEL TOP GARNISH <i>de</i>	1		\$ 244.00	244
32	REAR SMART LOCK ANTENNA <i>x</i>	1		\$ -	
33	REAR INNER SMART LOCK ANTENNA <i>x</i>	1		\$ -	
34	SPAREWHEEL PANEL <i>x</i>	1		\$ -	
35	SPAREWHEEL PANEL TOP BOARD <i>de</i>	1		\$ 380.00	380
36	EXHAUST PIPE <i>x n</i>	1		\$ 1,348.00	
37	EXHAUST MOUNTING SET <i>x</i>	2		\$ -	

8244
10% 7419.60

8244
10% 7419.60

38 EXHAUST HEAT SHIELD	1		\$	-	
			Total	\$ 13,441.00	13,441.00
			Less 10%	\$	-
			Total	\$ 12,069.90	12,096.90

S/Nett Items					
1	TAILGATE WINDSCREEN SEALANT	1	120	\$ 60 ea	120.00
2	TAILGATE INNER TRIM CLIPS SET	1	100	\$ X n7	100.00
3	TAIL LAMP CLIPS SET	1	40	\$ 20	40.00
4	REAR BUMPER CLIPS SET	1	100	\$ 30 ea	100.00
5	REAR NUMBER PLATE	1	100	\$ 67 45	100.00
6	REAR FENDER INNER TRIM CLIPS SET	1	100	\$ X n7	100.00
7	REAR FENDER COWLING CLIPS SET	1	100	\$ X n7	100.00
8	END PANEL SEALANT	1	250	\$ 40 ea	250.00
9	END PANEL TOP GARNISH CLIPS SET	1	100	\$ 10 ea	100.00
10	SPAREWHEEL PANEL SEALANT	1	300	\$ X n7	300.00
			Total	\$	1,310.00

LABOUR					
1	PANEL BEATING ON AFFECTED AREAS	1	2200	\$ 700 800	2,200.00
2	SPRAY PAINT ON AFFECTED AREAS	1	1400	\$ 200 800	1,400.00
3	TO RNR REAR EXHAUST	1	250	\$ X n7	250.00
4	TO CHECK WIRING AND TAIL LAMP FUNCTION	1	150	\$ 7 30	150.00
5	TO CHECK WIRING AND TAILGATE LAMP FUNCTION	1	150	\$ 30	150.00
6	TO UNLOAD AND UPHOISTERY REAR BOOT	1	400	\$ 60	400.00
7	TO CHECK WATER LEAK	1	150	\$ X 7	150.00
8	TO RNR FUEL TANK	1	250	\$ X 7 n7	250.00
9	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS	1	800	\$ X 7	800.00
10	TO RNR REAR TAILGATE MECHANISM	1	350	\$ 60	350.00
11	TO RNR REAR REVERSE SENSOR AND CHECK FUNCTION	1	150	\$ 30	150.00
12	TO PERFORM RUST PROOFING	1	400	\$ 30	400.00
			Total		

7419.60	Parts Replacement Amount	\$	1,310.00
205	Total Amount For Labour	\$	6,650.00
1810			20,029.90
9434.60	Total Amount	\$	7,960.00

Tanfah 97495749 4/5 \$7500
 WP 11/3/21 @ 3pm
 4/5 Resurvey after up
 Tanfah @ 11hants.com
 6 days

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

9907.40

2000