

AP Automotive Services

AP AUTOMOTIVE SERVICES PTE LTD
ROC: 202022890H
BLOCK 9006
TAMPINES STREET 93 #01-202
SINGAPORE 528840
TEL: 6784 4465
FAX: 6787 4886

Estimation

Date
Vehicle SKJ 749 R
Make/Model VOLKSWAGEN BEETLE
Chassis No.

No.	Description	Unit	Unit Price	Amount	
	Parts Replacment				
1	TAILGATE <i>ar bt</i>	1	(1388)	\$ 1,588.00	1388
2	TAILGATE WINDSCREEN MOULDING <i>rel</i>	1		\$ 227.00	227
3	TAILGATE CENTER LAMP <i>x n</i>	1		\$ 156.00	
4	TAILGATE LOGO OPENER <i>x n</i>	1		\$ 580.00	
5	TAILGATE EMBLEM - BEETLE <i>rel</i>	1		\$ 136.00	136
6	TAILGATE LOCK <i>x n</i>	1		\$ 186.00	
7	TAILGATE LOCK CATCH <i>x n</i>	1		\$ 90.00	
8	TAILGATE TRIM <i>x n</i>	1		\$ 318.00	
9	TAILGATE HINGE SET <i>x</i>	2		\$ -	
10	TAILGATE DAMPER SET <i>x n</i>	2	124.00	\$ 248.00	
11	TAILGATE WEATHERSTRIP <i>int</i>	1		\$ 324.00	324
12	TAIL LAMP L+R <i>LH x n RH - int</i>	2	270.00	\$ 540.00	270
13	TAIL LAMP LOWER BRACKET L+R <i>x n</i>	2	58.00	\$ 116.00	
14	REAR BUMPER <i>de</i>	1	1386	\$ 1586.00	1386
15	REAR BUMPER NUMBER PLATE LAMP L+R <i>int</i>	2	28.00	\$ 56.00	56
16	REAR BUMPER TOW COVER <i>x n</i>	1		\$ 30.00	
17	REAR BUMPER REVERSE SENSOR SET <i>n</i>	4	223.00	\$ 892.00	650
18	REAR BUMPER REFLECTOR L+R <i>x n</i>	2		\$ -	
19	REAR BUMPER LOWER <i>de</i>	1		\$ 174.00	174
20	REAR BUMPER RETAINER L+R <i>one</i>	2	102.00	\$ 204.00	204
21	REAR BUMPER CENTER BRACKET <i>de</i>	1		\$ 74.00	74
22	REAR BUMPER REINFORCEMENT BAR <i>bt</i>	1		\$ 686.00	686
23	REAR BUMPER LOWER BRACKET L+R <i>x LH n RH - int</i>	2	129.00	\$ 258.00	129
24	REAR BUMPER SPONGE <i>x</i>	1		\$ -	
25	REAR FENDER L+R <i>x</i>	2		\$ -	
26	REAR FENDER AIR VENT L+R <i>x</i>	2		\$ -	
27	REAR FENDER INNER TRIM L+R <i>x LH n RH - int</i>	2	748.00	\$ 1,496.00	748
28	REAR FENDER COWLING L+R <i>x LH n RH - int</i>	2	236.00	\$ 472.00	236
29	END PANEL <i>bt</i>	1	(932)	\$ 1,032.00	932
30	END PANEL AIR VENT <i>x n</i>	1		\$ -	
31	END PANEL TOP GARNISH <i>de</i>	1		\$ 244.00	244
32	REAR SMART LOCK ANTENNA <i>x</i>	1		\$ -	
33	REAR INNER SMART LOCK ANTENNA <i>x</i>	1		\$ -	
34	SPAREWHEEL PANEL <i>x</i>	1		\$ -	
35	SPAREWHEEL PANEL TOP BOARD <i>de</i>	1		\$ 380.00	380
36	EXHAUST PIPE <i>x n</i>	1		\$ 1,348.00	
37	EXHAUST MOUNTING SET <i>x</i>	2		\$ -	

8244
10% 7419.60

8244
10% 7419.60

38 EXHAUST HEAT SHIELD	1		\$	-	
			Total	\$ 13,441.00	13,441.00
			Less 10%	\$	-
			Total	\$ 12,069.90	12,069.90

S/Nett Items					
1 TAILGATE WINDSCREEN SEALANT	1	120	\$ 60.00	120.00	
2 TAILGATE INNER TRIM CLIPS SET	1	100	\$ X 1.00	100.00	
3 TAIL LAMP CLIPS SET	1	40	\$ 2.00	40.00	
4 REAR BUMPER CLIPS SET	1	100	\$ 30.00	100.00	
5 REAR NUMBER PLATE	1	100	\$ 6.45	100.00	
6 REAR FENDER INNER TRIM CLIPS SET	1	100	\$ X 1.00	100.00	
7 REAR FENDER COWLING CLIPS SET	1	100	\$ X 1.00	100.00	
8 END PANEL SEALANT	1	250	\$ 40.00	250.00	
9 END PANEL TOP GARNISH CLIPS SET	1	100	\$ 10.00	100.00	
10 SPAREWHEEL PANEL SEALANT	1	300	\$ X 1.00	300.00	
		Total	\$	1,310.00	

LABOUR					
1 PANEL BEATING ON AFFECTED AREAS	1	2200	\$ 2.00	2,200.00	
2 SPRAY PAINT ON AFFECTED AREAS	1	1400	\$ 1.00	1,400.00	
3 TO RNR REAR EXHAUST	1	250	\$ X 1.00	250.00	
4 TO CHECK WIRING AND TAIL LAMP FUNCTION	1	150	\$ 1.00	150.00	
5 TO CHECK WIRING AND TAILGATE LAMP FUNCTION	1	150	\$ 1.00	150.00	
6 TO UNLOAD AND UPHOISTERY REAR BOOT	1	400	\$ 1.00	400.00	
7 TO CHECK WATER LEAK	1	150	\$ X 1.00	150.00	
8 TO RNR FUEL TANK	1	250	\$ X 1.00	250.00	
9 TO PERFORM DIAGNOSTIC AND CLEAR FAULTS	1	800	\$ X 1.00	800.00	
10 TO RNR REAR TAILGATE MECHANISM	1	350	\$ 1.00	350.00	
11 TO RNR REAR REVERSE SENSOR AND CHECK FUNCTION	1	150	\$ 1.00	150.00	
12 TO PERFORM RUST PROOFING	1	400	\$ 1.00	400.00	
		Total			

7419.60	Parts Replacement Amount	\$	1,310.00	
205	Total Amount For Labour	\$	6,650.00	
1810			20,029.90	20,056.90
9434.60	Total Amount	\$	2,960.00	

WP 11/3/21 @ 5 pm
 1/5 Resurvey after repair
 6 days
 1/5 \$ 7500
 06 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

9907.40