



CYCLE & CARRIAGE

AG - OD (REVERT)
SURVEY: 09/03/21
LKK - STEVE

VEHICLE NO : SMX 6892Y

MODEL : KIA/NIRO 1.6 A SX

WIP : 30182

Material	:	\$	<u>3,379.20</u>
Labour	:	\$	<u>2,020.00</u>
Sub-Total	:	\$	<u>5,399.20</u>
Less 2% Disc	:	\$	<u>—</u>
Less Excess	:	\$	<u>600.00</u>
Total	:	\$	<u>4,799.20</u>
GST 7%	:	\$	<u>335.94</u>
Grand Total	:	\$	<u>5,135.14</u>
Finalise By/Date : <u>Larry on 18/03/21</u>			



REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING



SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 04 WORKING DAYS + 2 days (wk end)



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**PRO-FORMA INVOICE**

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 10/03/2021	Cust No/Name /KANAN CHIDAMBARAM Reg No/Reg Date SMX6892Y*ECB2/ 26/01/2021 Date In/Mileage 10/03/2021/ 1999 Chassis/Package KNACC81CVL539294E /# Engine No G4LELS647163 Make/Model KIA/NIRO 1.6 A SX SR AVT PE Colour/Trim KLG STEEL GREY / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	18/03/2021/ 11:13	BLE	884 / Lauro Songcuan	30182
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
E PNT88000	RENEW FRONT BUMPER & RH FRONT FENDER				800.00 ✓
E PNT98000	SPRAY PAINT FRONT BUMPER & RH FRONT FENDER				700.00 ✓
A 54900099	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				30.00 ✓
A 10028901	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00 ✓
M SUNDRY	SUNDRIES				20.00 ✓
E PNT98000	SPRAY PAINT SKID PLATE FRONT BUMPER				350.00 X
X EXC	EXCESS				-600.00
X	PANEL-FENDER,RH ✓	1.00	385.00	20.00	308.00 ✓
X	GARNISH ASSY-FNDR SIDE,RH ?	1.00	123.00	20.00	98.40 ?
X	LOGO ASSY-KIA SUB ✓	1.00	51.00	20.00	40.80 ✓
X	COVER-FR BUMPER UPR ✓	1.00	637.00	20.00	509.60 ✓
X	COVER-FR BUMPER,LWR ✓	1.00	373.00	20.00	298.40 ✓
X	COVER ASSY-RADIATOR GRILLE UPR ✓	1.00	40.00	20.00	32.00 ✓
X	GRILLE ASSY-RADIATOR X	1.00	441.00	20.00	352.80 ?
X	PIECE-FRT BUMPER GUARD LWR,LH X	1.00	16.00	20.00	12.80 ?
X	PIECE-FRT BUMPER GUARD LWR,RH ✓	1.00	16.00	20.00	12.80 ✓
X	LAMP ASSY-HEAD,RH ✓	1.00	2102.00	20.00	1681.60 ✓
X	NIRO HYBRID EMBLEM	1.00	30.00	20.00	24.00 X
X	CLIP	10.00	1.00	20.00	8.00 X
Z TEXT	OD CLAIM - AIG SURVEY: STEVE (LKK) 09.03.2021 DOA: 08.03.2021 04 DAYS				
Guarantee Your Warranty, Maintain with Cycle & Carriage!					

Parts	3,379.20	Nett	4,799.20
Labour	2,000.00	7% GST on	335.94
Standard Menu	0.00		
Specialist Job	0.00		
Diagnostics Job	0.00	Total Payable	5,135.14
Sundry/Others	-580.00		
Total(w/o GST)	4,799.20		

This is not an official tax invoice.
This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

INSURANCE CO. : AIG

Supplementary For Registration No.: SMX 6892 Y

<u>Materials</u>		<u>Cost \$</u>
1	NIRO Hybrid Emblem	30.00 ✓ <i>NEC</i>
2	Clip (10 pcs)	10.00 ✓ <i>NEC</i>
		40.00
20% Discount		8.00
		32.00
<u>Labour</u>		
1	Spray Paint Skid Plate Front Bumper	350.00 ✓
		382.00
7% GST		26.74
Total		408.74

Thank You.

Yours faithfully
CYCLE & CARRIAGE KIA PTE LTD

Larry Songcuan
Customer Service
Cycle & Carriage
Pandan Gardens

CAR NO: SMX6892YWIP: 30182

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	GRNICH FENDER SIDE RH	? / SUPP			
2	PLECT FRT BUMPER SIDE LH	? / SUPP			
3	BUMPER CLIP (x10)	? / SUPP			Steve
4	STRAY SKID PLATE FRT BUMPER	? / SUPP			11/3/21
5	GRILLE ASSY-RADIA TOR	? / SUPP			15/3/21
6		? / SUPP			
7		? / SUPP			
8		? / SUPP			
9		? / SUPP			
10		? / SUPP			
11		? / SUPP			
12		? / SUPP			
13		? / SUPP			
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

PHOTO BEFORE PAINT	DATE	TAKEN BY
PHOTO AFTER PAINT	15/3/21	Steve
PHOTO OF MOUNT TO CELLETE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBAORD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: NIROSURVEYOR: STEVE

HOME Online Niro(DE HEV)/2020/G 1.6 GDI.. VCI

Fault Code Searching

Rescan Erase All DTC Go to DTC Save

27/27

System	Status	Result
ENGINE	No Current DTC	Good
MCU	No Current DTC	Good
HCULDC	No Current DTC	Good
BMS	No Current DTC	Good
AT	No Current DTC	Good
EPB	No Current DTC	Good

System	DTC	Description	State
No History or Pending DTC			

S/W Ver.	M-E-K-01-00-0241	VCI Ver.	02.51
ECU Ver.	M-E-K-01-00-0182	OS Ver.	Android 10

HOME
 Online
Niro(DE HEV)/2020/G 1.6 GDI..
VCI

Fault Code Searching

Rescan

Erase All DTC

Go to DTC

Save

8/8

System	Status	Result
ENGINE	No Current DTC	Good
MCU	No Current DTC	Good
HCULDC	No Current DTC	Good
BMS	No Current DTC	Good
AT	No Current DTC	Good
EPB	No Current DTC	Good

System	DTC	Description	State
No Current DTC			

S/W Ver.	M-E-K-01-00-0241	VCI Ver.	02.51
ECU Ver.	M-E-K-01-00-0182	OS Ver.	Android 10