

5-21

King's Auto Spray Paint Pte Ltd
Blk 160 Sin Ming Drive #05-10

Sin Ming Autocity Singapore 575722 11 Pump @ 3000dp

Not Notarised
Running After Pay

Re: Estimate cost for SJB6228S HONDA CIVIC 5days

SUPPLY OF PARTS:

1pc rear boot lid	R \$ 580.20 ✓
1pc rear boot lid center garnish	ms car 110.80 ✓
1pc rear center garnish logo	ms 14.90 ✓
1pc rear center garnish CIVIC emblem	ms 14.50 ✓
1pc rear center garnish iVTEC emblem	ms 15.50 ✓
1pc rear boot lid lock	ms 82.00 X
1pc rear boot lid rubber	ms 70.00 ✓
1pc rear boot lid inner trim	ms 68.00 X
10pc rear inner trim clips @ 4.50	ms 45.00 X
2pc rear tail lamp @ 350.50	ms 701.00 ✓
1pc rear tail lamp lower retainer	ms 18.00 ✓
1pc rear bumper	R 650.50 ✓
2 4pc rear bumper sensor @ 140.40	short 561.60 2H
1pc rear bumper lower spoiler	ms 200.00 ✓
1pc rear spoiler cover	ms 20.00 X
6pc rear spoiler clips @ 3.50	ms 21.00 ✓
1pc rear bumper beam	R 160.00 ✓
2pc rear bumper side retainer @ 15.00	ms 30.00 ✓
8pc rear bumper clips @ 3.50	ms 28.00 ✓
1pc rear bumper side reflector	ms 10.50 X
1pc rear side reflector grille	ms 19.30 ✓
1pc rear center panel	R 265.00 ✓
1pc rear center panel top trim	ms 80.30 X
6pc rear top trim clips @ 4.50	ms 27.00 X
1pc rear camera	ms \$ 550.00 X
	\$ 4343.10
	868.62
	\$ 3474.48

Less 20%

9-3-21

King's Auto Spray Paint Pte Ltd
Blk 160 Sui Ming Drive #05-10
Sui Ming Autocity Singapore 575722

Balance b/f

3474.48

1pc Rear number plate

~ \$ 40 X

LABOUR:

Renew the above mentioned parts
Knocking, cutting, welding & straighten
rear damaged parts

\$ 900 ~~88d~~

spray paintings

\$ 900 ~~86d~~

5314.48

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: