

INS. CASE OWNER:

barnald CC 3 / LPC1700

2778, KI YG3

LKK:  
IDAC:

Surveyor:

Kalvin

DOI:

ASSIGNMENT

10/2/17

Date / Time:

10/2/17

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SJB 7011L

Name of Insured:

Lim Bee Bu

Insured Tel No.:

HP:

9119 8801

Excess Sec II :SS

D.O.A.:

6/2/17

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Lim Seng Gi

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

17/17/17/VP05/019676

Policy No.:

217VP05013016

Make / Model:

Hyundai Avante - 1.6 199

Place of Accident:

Upper Blt Timah road

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final? Yes / No

SMB 1649H



INSRS:

WSP:

Tel:

Liability:

RMKS:

SMB 7011L



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

13/2/17

SMB 1649H - X  
SJB 7011L - (CH/LA/1602326/1600 3 0004/14/16)

potential reject -

22/11/17 @ 11:50 File pass to typist to prepare report

RECEIVED 15 JAN 2018

Project Logo  
Approved by: gas  
Date: 11-01-18

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

830

(102 days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

50

(Agreed / Assessed) BOLA S/N No.:

Nil

If NO or B 28, Ass. Lia:

Repair Cost:

830.00

SS

415.00

Loss of Rental (LOR):

SS

( )

( days)

Loss of Use (LOU):

550.00

SS

275.00 (\$ 275 x 2 days)

Loss of Income (LOI):

SS

(\$ )

(x days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

SS

5.00

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

Total:

SS

695.00

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

Name 1:

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

450/-





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC3/LPC17002778/K1yg3

100 BEACH ROAD  
#19-00 SHAW TOWERS SINGAPORE 189702

Date : 10-02-2017



Code : LPC2

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJB 7201L	Veh. Inspected	SMB 1649H
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	10/02/2017

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--	--

## 5. General Information

Accident Date	06/02/2017	Inspection Date	10/02/2017
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
---

2143269



NRIC No. S1404147H



Blood Group: B+      Date of issue: 17-06-1994

Address:  
APT BLK 270 TOH CHUAN ROAD #13-103  
SINGAPORE 600270

NRIC No: S1404147H      Date: 02-02-1998      No: 2472010

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

CLASS	VEHICLE CLASS	VALID DATE
Class 1B	Motorcycles < 300 CC	31 Oct 1993
Class 2	Motor cars < 2000 kg with < 7 passenger seats, exclusive of the driver and motor-driven tricycles < 2000 kg	13 Jun 1994
Class 4A	Omni-buses	04 Mar 2013

S1404147H      S/No. 9000178772

License No: S1404147H

NP 428A

## SMRT Accident Vehicle Repair Estimates


### Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SMB1649H  
Ref. No : BUS/02/17/5004  
Reg. Date : 27/02/2015  
Vehicle Type : BUS -12M  
Make : MAN  
Model : MAN  
Name of Driver : Han Cann Chour  
Type of Accident : SIDE SWIPE  
Date / Time of Accident : 06/02/2017 12:20:00 PM  
Accident Reported Date / Time : 07/02/2017 12:00:00 AM  
Surveyor is Required? : Yes  
Survey by : Lonpac Ins Bhd  
Vehicle is Towed Back? : No  
Towed Back Date/Time : 01/01/2000  
Replacement Vehicle issued? : No  
Accident Repair Job Card No : 000024087885  
Special Instruction to ARC,if any :

RIGHT FRONT PORTION.

TP: SJB7201L - LONPAC INSURANCE

Prepared Date : 07/02/2017 04:42:50 PM



**Section B - To be Completed by Service Advisor, Accident Repair Centre**

Chassis No : WMAA22ZZ7F7002651

Mileage :

0

Work Shop :

Repair Completed Date / Time : 01/01/2000

**Summary of Repair Estimates****Quotation from ARC****Adjusted by Surveyor, if applicable**

Total Labour Charges : 795.00

530.00

Total Spray Painting Charges : 446.00

300.00

Total Material Charges : 0.00

0.00

Other Charges : 0.00

0.00

**TOTAL** : **1,241.00****830.00****Lum Sum Total** : **0.00****0.00**

No. of Repair Days : 3.00

2.00

Prepared / Adjusted By : Goh Kok Khoo

Kalvin (LKK)

Arc / Surveyor Sign Off Date : 10/02/2017 03:05:48 PM

10/02/2017 03:08:27 PM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 10/02/2017 03:05:48 PM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date :

**Section D - Details of Repair Estimates****Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH FRONT PORTION	795.00	530.00
<b>Total Labour</b>	<b>795.00</b>	<b>530.00</b>

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	446.00	300.00
<b>Total Spray Painting &amp; Panel Beating</b>	<b>446.00</b>	<b>300.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expenses**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
<b>Total Other Costs</b>		

**Part 4 - Spare Parts / Material Usage**

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
<b>TOTAL MATERIALS</b>										
<b>TOTAL MATERIALS(Discounted)</b>								<b>0.00</b>	<b>0.00</b>	

**Added Spare Parts / Material Usage After Surveyor Signed off**

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
<b>TOTAL SUPPLEMENTARY MATERIALS</b>									

parts - 0  
 labor - 830  


---

 total - \$830  


---


 confirm  
 11/22/12



## SMRT Accident Vehicle Repair Estimates

### Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SMB1649H  
 Ref. No : BUS/02/17/5004  
 Reg. Date : 01/01/1900  
 Vehicle Type : BUS -12M  
 Make : MAN  
 Model : MAN  
 Name of Driver : Han Cann Chour  
 Type of Accident : SIDE SWIPE  
 Date / Time of Accident : 06/02/2017 12:20:00 PM  
 Accident Reported Date / Time : 07/02/2017 12:00:00 AM  
 Surveyor is Required? : Yes  
 Survey by : LKK  
 Vehicle is Towed Back? : No  
 Towed Back Date/Time :  
 Replacement Vehicle issued? : No  
 Accident Repair Job Card No :  
 Special Instruction to ARC,if any :  
 RIGHT FRONT PORTION.  
 TP: SJB7201L - LONPAC INSURANCE  
 Prepared Date : 07/02/2017 04:42:50 PM



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

**Section D - Details of Repair Estimates****Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	795.00	530.00
<b>Total Labour</b>	<b>795.00</b>	<b>530.00</b>

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	446.00	300.00
<b>Total Spray Painting &amp; Panel Beating</b>	<b>446.00</b>	<b>300.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expenses**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
<b>Total Other Costs</b>		

**Agnes Lim (LKKAUTO)**

---

**From:** GERALD POH WEE BIN <geraldpoh@lonpac.com>  
**Sent:** Monday, 13 February, 2017 12:29 PM  
**To:** Agnes Lim (LKKAUTO)  
**Cc:** MT\_Claim\_SG  
**Subject:** RE: Direct Settlement - Accident Involving SJB7201L (OI: LPC - TBA) and SMB1649H (TP: LKK REF - CC3/LPC17002778/K1yg3) on 06.02.2017  
**Attachments:** 13022017122602.pdf

Our Ref : 17/17/17/VP05/019676

Dear Shu Pei,

We attached a copy of insured's GIA report for your attention.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd  
100 Beach Road, #19-00 Shaw Tower, Singapore 189702  
Tel: (65) 6250 7388 Ext.240 | Fax: (65) 6296 2706

---

**From:** Agnes Lim (LKKAUTO) [mailto:AgnesLim@lkkauto.com]  
**Sent:** Monday, 13 February, 2017 12:13 PM  
**To:** GERALD POH WEE BIN  
**Cc:** MT\_Claim\_SG; ONG LI LI; Jas Khine (LKKAUTO); VIC (LKKAUTO); Admin A  
**Subject:** Direct Settlement - Accident Involving SJB7201L (OI: LPC - TBA) and SMB1649H (TP: LKK REF - CC3/LPC17002778/K1yg3) on 06.02.2017

**WITHOUT PREJUDICE**

Dear Sir / Madam,

We refer to the above matter.

This is a TP direct settlement case.

We had inspected TP vehicle SMB 1649H at M/s SMRT Automotive Services Pte Ltd (Woodlands) - Woodlands.

Enclosed for your perusal is:

- TP GIA report
- TP estimate
- Preliminary advice

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Jas and she can be contacted at 6844 2928.

Thank you.

To check availability of the case handler, you may contact the undersigned.

Best Regards,

**Agnes Lim** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6366-0055 | email: [AgnesLim@lkkauto.com](mailto:AgnesLim@lkkauto.com) | fax: 6741-4148

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | 5(408933)



AR REGISTERED

Lonpac Insurance Bhd  
Singapore Branch 100,  
Beach Road #19-00  
Shaw Tower Singapore 189702

SMRT AUTOMOTIVE SERVICES PTE LTD  
60 Woodlands Industrial Park E4  
Singapore 757705  
Tel : 65 6866 2652  
Fax : 65 6368 7421  
www.smr.com.sg

Via LKK - Jas Khine / Surveyor Kalvin

Date : 1 MARCH 2017  
Our Ref. BUS/02/17/5004 /AW

Dear Sirs,

**ACCIDENT INVOLVING SMB1649H AND SJB7201L ON 6 FEB 2017 ALONG UPPER  
BUKIT TIMAH ROAD.**

LETTER OF CLAIM

We claim on behalf of **SMRT BUSES LTD**, owner/hirer of the vehicle Reg. No.: **SMB1649H**. Your driver's negligent driving has caused the above accident. As a result, my client has suffered the following losses:-


1. Cost of Repair	:	\$ 830.00
2. Loss of Use for 2 days @ S\$ 275 /day	:	\$ 550.00
3. Loss of Rental for _____ days @ S\$ _____ /day	:	_____
4. Loss of Income for _____ days @ S\$ _____ /day	:	_____
5. Police Report/ SAS Report/ LTA Search Fee	:	\$ 5.00
6. Survey Fee	:	_____
7. Others	:	_____
Total Claims :		<b>\$ 1385.00</b>

We enclose the following documents :

- |  |   |
|--|---|
| <input checked="" type="checkbox"/> Repair Invoice               | <input type="checkbox"/> Letter of Authorisation      |
| <input type="checkbox"/> Survey Report                           | <input checked="" type="checkbox"/> LTA Search result |
| <input type="checkbox"/> Photographs _____ pcs                   | <input checked="" type="checkbox"/> Others :          |
| <input type="checkbox"/> Investigation results                   | 1. <u>LAID UP REPORT</u>                              |
| <input type="checkbox"/> Proof of Loss of Use/Rental/Income      | 2. <u>Copy of Bus Driver's Driving License</u>        |
| <input checked="" type="checkbox"/> Police / SAS report of _____ | 3. _____  |

We look forward to your confirmation to settle our claims within 15 days from the date of this letter. Payment by cheque shall be crossed and made payable to **SMRT BUSES LTD**

Yours sincerely,  
SMRT AUTOMOTIVE SERVICES PTE LTD

  
Audrey Woo  
For Manager, Claims  
Claims Department



Customer Code: 3000066

SMRT BUSES LTD

Block Unit  
STREET 62  
6 ANG MO KIO  
SINGAPORE 569140



SMRT Automotive Services Pte Ltd  
251 North Bridge Road Singapore 179102  
Tel: 65 63311000 Fax: 65 63340247

### Tax Invoice

GST Reg No. : MR-8500001-7  
CRN : 199004280Z  
Invoice No. : IV170200556  
Date : 23.02.2017  
Vehicle No. : SMB1649H  
Your Ref No. : BUS/02/17/5004  
Our Ref No. : 24087885  
Terms : 30 Days

Description	Qty	Unit Cost	Add %	/ (Discount) Amount		Amount
Labour						
TO REPAIR RH FRONT PORTION	1.00	\$ 530.00	0.00	\$	0.00	\$ 530.00
Others						
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	1.00	\$ 300.00	0.00	\$	0.00	\$ 300.00

GRAND TOTAL \$ 830.00

Remark :

Make/Model : MAN  
Accident Date : 06.02.2017

N.B. Payment by cheque should be crossed and  
made payable to 'SMRT Automotive Services Pte Ltd'.  
No receipt will be issued unless requested.

Authorised Signature  
for SMRT Automotive Services Pte Ltd



# Accident Vehicle Laid-Up Report

Registration No. : SMB1649H

Accident Case No. : BUS/02/17/5004

Make / Model : MAN NL320F(A22)

Ref. No. : 24087885

Date and Time Vehicle off-road for Accident Repair : 16.02.2017 13:06:23

Date and Time Repair Completed : 17.02.2017 15:02:06

Remarks :

Generated by : CATHERINELEE

Printed on : 21.02.2017

Text size + -

**Enquire Transaction History****Transaction History Details**

Log Date/Time: 07 Feb 2017 / 15:50:37

Asset Type: Vehicle

Transaction Amount: \$5.35

Asset ID: SJB7201L

Transaction Type: 18.32 Insurance Enquiry (GIRO Payment)

Channel: External Agency

User ID: ESASBAH0 - BALQISH BINTE ABDUL HALIL

Business Transaction Reference No.: 20170207155037770978

Search Date / Time: 06 Feb 2017 12:20:00

Insurance Company: LONPAC INSURANCE BHD

Information displayed is correct as at the log date and time.

[Enquire Related Logs](#)[Back to List](#)

Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.

Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above, 1024 X 768 resolution

Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#)



## Jas Khine (LKKAuto)

---

**From:** Jas Khine (LKKAuto)  
**Sent:** Thursday, 11 January 2018 2:10 PM  
**To:** Audrey Woo (Auto Svcs/Claims) (audrey@smrt.com.sg)  
**Subject:** ACCIDENT INVOLVING SMB 1649H & SJB 7201L ON 06/02/2017  
**Attachments:** OUR INSURED ACCIDENT STATEMENT.pdf; our insured vehicle damage photo.pdf

### WITHOUT PREJUDICE

Your Ref: BUS/02/17/5004/AW  
Our Ref : CC3/LPC17002778/K1yg3

Dear Audrey,

### **ACCIDENT INVOLVING SMB 1649H & SJB 7201L ON 06/02/2017**

We refer to the above matter.

The accident occurred due to the negligence of your client's vehicle was moving out from bus bay and collided to our insured vehicle which was passing by (oncoming vehicle).

Based on damages sustained to both vehicles, it's clearly showed that your client's vehicle was slanting position at the time of the collision and hit onto our insured vehicle while passing by. If both vehicles side swipe as alleged by your client, his vehicle should have the scratched marks on its' body as well. However, damages sustained onto its front right corner only.

Therefore, we regret to inform you that we have our Principal instruction to deny the liability and unable to look into your client's claim.

Thank you.

Best Regards,  
Jas Khine | Case Handler  
LKK Auto Consultants Pte Ltd  
Phone: 6841-2928 | email: jaskhine@lkkauto.com | fax: 6741-4108  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## Jas Khine (LKKAuto)

**From:** ONG LI LI <llong@lonpac.com>  
**Sent:** Tuesday, 19 December 2017 11:36 AM  
**To:** Jas Khine (LKKAuto)  
**Cc:** MT\_Claim\_SG  
**Subject:** RE: your ref: 17/17/17/VP05/019676Accident Involving SJB7201L and SMB1649H ...MANDATE REQUEST TO REJECT TP CLAIM

**Follow Up Flag:** Follow up  
**Flag Status:** Completed

Dear Jas

Please go ahead with your recommendation.

Regards,  
Ong Li Li  
Senior Claims Executive | Lonpac Insurance Bhd  
300 Beach Road #17-04/07 The Concourse Singapore 199555  
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706


---

**From:** Jas Khine (LKKAuto) [mailto:jaskhine@lkkauto.com]  
**Sent:** Tuesday, 19 December, 2017 10:59 AM  
**To:** ONG LI LI  
**Cc:** MT\_Claim\_SG  
**Subject:** your ref: 17/17/17/VP05/019676Accident Involving SJB7201L and SMB1649H ...MANDATE REQUEST TO REJECT TP CLAIM


Dear Li Li,

We refer to the above matter and as discussed earlier.

TP reported that he was travelling straight along Upper Bukit Timah Road towards Tampines at extreme left lane, suddenly our insured vehicle trying to overtake his bus and side swipe to his right front portion.



OI reported that TP was moving out from bus bay and collided to his vehicle while he passing by the bus stop.



A - SJB 7201L (Insd).  
B - SMB 1649H

We have requested TP to provide evidence for our further consideration. However, TP unable to provide any evidences.

Based on damages sustained to both vehicles, we are of the opinion that at the time of the collision TP vehicle was slanting position. TP bus sustained damages onto right front corner and our insured vehicle sustained long grazed marks along its left side body, it's subjected that one vehicle is slanting position at the time of the collision. If both vehicles side swipe as alleged by Third Party, his bus should not be sustained damage on its right front portion corner only but also should have damages on its right side body.

Therefore, our insured version is more probable and we are intending to reject Third Party claim.

Kindly let us have your view/instruction/comments if any.

Thank you.

Best Regards,

**Jas Khine** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2928 | email: [jaskhine@lkkauto.com](mailto:jaskhine@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Agnes Lim (LKKAuto)

**Sent:** Monday, 13 February, 2017 12:13 PM

**To:** [geraldpoh@lonpac.com](mailto:geraldpoh@lonpac.com)

**Cc:** MT\_Claim\_SG <[mt\\_claim@lonpac.com](mailto:mt_claim@lonpac.com)>; 'ONG LI LI' <[long@lonpac.com](mailto:long@lonpac.com)>; Jas Khine (LKKAuto) <[jaskhine@lkkauto.com](mailto:jaskhine@lkkauto.com)>; Vic (LKKAuto) <[vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com)>; Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>

**Subject:** Direct Settlement - Accident Involving SJB7201L (OI : LPC - TBA) and SMB1649H (TP : LKK REF - CC3/LPC17002778/K1yg3) on 06.02.2017

#### **WITHOUT PREJUDICE**

Dear Sir / Madam,

We refer to the above matter.

This is a TP direct settlement case.

We had inspected TP vehicle SMB 1649H at M/s SMRT Automotive Services Pte Ltd (Woodlands) - Woodlands.

Enclosed for your perusal is:

- TP GIA report
- TP estimate
- Preliminary advice

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Jas and she can be contacted at DID: 6841 2928.

Thank you.

*To check availability of the case handler, you may contact the undersigned.*

Best Regards,

Agnes Lim | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6366-0055 | email: [AgnesLim@lkkauto.com](mailto:AgnesLim@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC3/LPC17002778/K1yb3n2

300 BEACH ROAD  
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 15-01-2018



Code : LPC2

**1. Policy Particulars :- THIRD PARTY CLAIM**

Insured Veh.	SJB 7201L	Veh. Inspected	SMB 1649H
Policy No.	Z17VP05013016	Coverage (\$)	0.00
Claim No.	17/17/17/VP05/019676	Excess (\$)	0.00
Assign From		Assign Date	10/02/2017

**2. Vehicle Particulars & Condition**

Make & Model	MAN NL 320F	c.c	10518
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	WMAA22ZZ7F7002651	Colour	SILVER
Odometer	178780	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

**3. Conditions of Tyres**

	Size	Make	Balance
R/H Front Tyre	275/70 R22.5	CONTINENTAL	4 mm
L/H Front Tyre	275/70 R22.5	CONTINENTAL	4 mm
R/H Rear Tyre	275/70 R22.5 (D)	CONTINENTAL	4/4 mm
L/H Rear Tyre	275/70 R22.5 (D)	CONTINENTAL	4/4 mm

**4. Description of Damages**

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.
---

**5. General Information**

Accident Date	06/02/2017	Inspection Date	10/02/2017
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

**5a. Remarks**

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

**5b. Estimate Days of Repair**

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>2 Working Days</b>
-------------------------------------	-----------------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMB 1649H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b>			
	TO REPAIR RH FRONT PORTION.		795.00	530.00
	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS.		446.00	300.00
			1,241.00	830.00
	<b>GRAND TOTAL</b>		<b>1,241.00</b>	<b>830.00</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>830.00</b>

Report Ref No. CC3/LPC17002778/K1yb3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.