## Massive Trading & Auto BIK 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541

H/P 91082728

Yeo Choon Kiong Blk 359 Yishun Ring Road #03-1700 Singapore 760359

Make : Mazda 3

Vehicle No : SGF 9992 M

Year

: 2018

Fax: 64816131

Not Nothanks

11 Rap & 3050h

Resony Afre Pains

5day

Qty	Description	Unit Price	Amount	
Estimate Co	st Of Repair			
1 pc	Front n/s door	1	\$1,200.40	
1 pc	Front n/s door inner lock	7 \$285.70 X		
1 pc	Front n/s door rubber	1	√a \$205.10 Y	
1 set	Front n/s door frame black sticker	~~ \$105.60 X		
1 pc	Rear n/s door 1085.90	B/Iwan	\$1,130.70	
1 set	Rear n/s door frame black sticker	n	\$105.60 -	
2 pcs	Rear n/s door hinge	\$105.10	7 \$210.20 x	
1 pc	Rear n/s door inner lock	* *	1 \$275.10 X	
1 pc	Rear n/s door rubber	1	\$195.70 X	
1 pc	Rear n/s door inner trim board	1	\$550.70 X	
1 pc	Rear n/s fender	nun	\$1,233.30 X	
1 pc	N/S rocker panel garnish	"IdlD"	\$624.30 -	
1 pc	Rear bumper	Mypis	\$996.80 7	
1 pc	Rear n/s bumper side retainer	,	\$75.60 X	
			\$7,194.80	
		Less 20 %	\$1,438.96	
			\$5,755.84	
Labour Char	<u>ges</u>			
Remove/rene	ew the above part including knocking, welding & cutting.		\$1,000.00	
To putty and spray paint on rear portion.			\$1,000.00	
To respray a	nti-rust proofing		\$60.00 30	
Check & reco			\$30.00 2	
Check a rece	Threat willing			
Remove/rene	ew rear exhaust silencer	N	~ \$120.00 X	
	LNN AUTO CONSULTANTS NENCE NOTIFY	Market State of the State of th		
Remove/refit	front & rear n/s door mechanism, door glass to new door painting		\$180.00	
verilove/relit	To display damaged part(s) during resurvey	Total	\$8,145.84	
	Parts prices are subject to confirmation			
	Third party survey is on a "Without Prejudice" basis			
	No illegal modification(s) is allowed			
	Supplementary item(s) must be resurveyed and			
	is subject to final approval from Insurance Company			

Acknowledged by Repairer

Signature: Date: