



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21003161/Uvd3q2	
			Date: 22/03/2021	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBG 2158E	Veh. Inspected	SLF 3729M
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2100768/SYH	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	10/03/2021
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA SIENTA (A)	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	NSP1707020225	Colour	BROWN
	Odometer	79344 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/50 R15	BRIDGESTONE	6 mm
	L/H Front Tyre	195/50 R15	BRIDGESTONE	6 mm
	R/H Rear Tyre	195/50 R15	BRIDGESTONE	6 mm
	L/H Rear Tyre	195/50 R15	BRIDGESTONE	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	09/03/2021	Inspection Date	11/03/2021
	Survey held at	JOO HAK KEE AUTO PTE LTD 3007 UBI ROAD 1 #01-406 KAMPONG UBI INDUSTRIAL ESTATE SINGAPORE 408701		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	