

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

205 Braddell Road
Singapore 579701
Tel: 63837168 /63837118 Fax: 62815767/65462533 Email: denisteo@cdge.com.sg

TP INSURER: India International Insurance Pte Ltd (HQ)
MOHAMED SAHRI BIN SAMSURI

Singapore

PARTICULARS OF CLAIM

Claim Type:	Third Party	Ref. No:	
Policy No:		Date of Loss:	05/03/2021
Vehicle Reg. No.:	SMP8377Y	Driveable?	
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI AVANTE, 1.6 (A)	Vehicle Reg. Date:	18/10/2019
Vehicle Colour:	Metallic Silver	Chassis No:	KMHD841CMLU965799
Engine No:	G4FGKU200987		
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	12 8-10 days		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (BRADDELL)		

*Not Notified
Missing B4 paint*

COST OF CLAIMS	Amount
Parts	13,705.12
Miscellaneous Items	11.00
Labour	4,990.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	18,706.12
+ GST 7.00% (S\$)	1,309.43
Nett Amount (S\$)	20,015.55

This claim is handled by: ANDREW CORNELIUS GOH CHENG CHUAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 10 Mar 2021)

Parts: 143

HYUNDAI AVANTE 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's

(Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SMP8377Y/10/03/2021 11:06

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*Rear number plate with casing	0	0.00	Ref *35.00 FS	✓
2	1		*Rear bumper	20.00	0.00	Bu *459.40 FL	✓
3	1		*Rear bumper clips	20.00	0.00	in *15.00 FL	✓
4	1		*Rear bumper side retainer LH	20.00	0.00	in *29.40 FL	X
5	1		*Rear bumper side retainer RH	20.00	0.00	*29.40 FL	?
6	1		*Rear bumper reinforcement	20.00	0.00	*294.80 FL	?
7	1		*Rear bumper lower skirt	20.00	0.00	CM *353.50 FL	✓
8	1		*Rear bumper reflector LH	20.00	0.00	in *201.50 FL	X
9	1		*Rear bumper reflector RH	20.00	0.00	*201.50 FL	?
10	1		*Reverse sensor	0	0.00	Ref *240.00 FS	✓
11	1		*Taillamp LH	20.00	0.00	in *1,052.10 FL	X
12	1		*Taillamp RH	20.00	0.00	in *1,052.10 FL	X
13	1		*Taillamp clips	20.00	0.00	nn *9.80 FL	X
14	1		*Taillamp lower panel LH	20.00	0.00	X *193.10 FL	X
15	1		*Taillamp lower panel RH	20.00	0.00	1 *193.10 FL	X
16	1		*Rear end panel	20.00	0.00	*454.60 FL	?
17	1		*Rear end panel garnish	20.00	0.00	*59.80 FL	?
18	1		*Rear end panel garnish clips	20.00	0.00	*10.00 FL	?
19	1		*Bootlid cover	20.00	0.00	B *1,782.40 FL	✓
20	1		*Bootlid lock	20.00	0.00	R *116.20 FL	X
21	1		*Bootlid weatherstrip	20.00	0.00	in *92.50 FL	X
22	1		*Bootlid inner trim centre	20.00	0.00	in *146.80 FL	X
23	1		*Emblem	20.00	0.00	nn *196.20 FL	✓
24	1		*AVANTE	20.00	0.00	nn *31.20 FL	✓
25	1		*Reverse camera	20.00	0.00	in *826.10 FL	X
26	1		*front number plate with casing	0	0.00	B *35.00 FS	✓
27	1		*Front bumper	20.00	0.00	CM *474.40 FL	✓
28	1		*Front bumper clips	20.00	0.00	in *20.00 FL	✓
29	1		*front bumper reinforcement	20.00	0.00	*695.80 FL	?
30	1		*Front bumper side retainer LH	20.00	0.00	in *13.70 FL	X
31	1		*Front bumper side retainer RH	20.00	0.00	Div *13.70 FL	✓
32	1		*Front bumper sponge	20.00	0.00	*110.70 FL	?
33	1		*Front bumper beam lower	20.00	0.00	*119.00 FL	?
34	1		*Front bumper protector center	20.00	0.00	*115.40 FL	?
35	1		*Front bumper protector LH	20.00	0.00	*115.40 FL	?
36	1		*Front bumper protector RH	20.00	0.00	*115.40 FL	?
37	1		*Front bumper tow cover	20.00	0.00	in *8.00 FL	X
38	1		*Front bumper lower lip	20.00	0.00	in *71.70 FL	X
39	1		*Fog lamp LH	20.00	0.00	in *164.80 FL	X
40	1		*Fog lamp RH	20.00	0.00	in *164.80 FL	X
41	1		*Fog lamp side grille LH	20.00	0.00	in *33.60 FL	X
42	1		*Fog lamp side grille RH	20.00	0.00	in *33.60 FL	X
43	1		*Headlamp LH	20.00	0.00	in *1,756.40 FL	X
44	1		*Headlamp RH	20.00	0.00	CM *1,756.40 FL	✓
45	1		*Front support panel	20.00	0.00	*949.30 FL	?
46	1		*Bonnet	20.00	0.00	B *1,970.70 FL	✓
47	1		*Bonnet lock	20.00	0.00	R *129.90 FL	X

1	*Grille emblem	20.00	0.00	<i>Na</i>	*26.20 FL
	*Front support top garnish	20.00	0.00	<i>CM</i>	*84.50 FL

Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	17,053.90
- List Item Discount on L Items (\$)	3,348.78
Total Parts (\$)	13,705.12

ComfortDelGro Engineering Pte Ltd/SMP8377Y/10/03/2021 11:06. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

Qty	Particulars	Amount
Miscellaneous Items		
1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)		11.00

Estimates on Labour

Particulars	Lab.Type	Amount
Labour Items		
TO CUT /WELD AND PANEL BEAT REAR END PANEL, REAR BUMPER, BOOTLID, FRONT BUMPER, BONNET, FRONT PANEL , REPLACE DAMAGE PARTS AND REALIGN AFFECTED AREAS	New	2,400.00
TO PUTTY ,RESPRAY ON REAR BUMPER,END PANEL,BOOTLID, FRONT BUMPER, BONNET , FRONT PANEL , DAMAGES AND AFFECTED AREAS	New	2,000.00
TO CHECK LIGHTING AND WIRING	New	120.00
TO INSTALL REVERSE SENSOR	New	120.00
TO TRANSFER BOOTLID PARTS AND MECHANISMS TO NEW BOOTLID	New	150.00
TO APPLY RUST PROOFING ON REPAIR AND REPLACE PANELS	New	200.00
Gross Labour Cost (S\$)		4,990.00

1200

1250

401

801

601

7

ComfortDelGro Engineering Pte Ltd/SMP8377Y/10/03/2021 11:06. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >