

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

Email: mg3solution@gmail.com

TO	: AXA	DATE	: 10-Mar-21
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SJY6177J		
MODEL	: SEAT LEON		Jasper.
CHASSIS NO			
<u>ACCIDENT DETAILS</u>		DATE	: 9-Mar-21
		TIME	: 07:55HRS
THIRD PARTY REQUESTOR / CONTACT : JACK LI			

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Rehd</i>	1	\$ 1,855.30	\$ 1,855.30
2	REAR BUMPER SIDE RETAINER <i>Rehd</i>	2	\$ 60.30	\$ 120.60
3	REAR BUMPER SIDE BRACKET <i>Rehd</i>	2	\$ 90.80	\$ 181.60
4	REAR BUMPER LOWER SPOILER <i>Rehd</i>	1	\$ 633.40	\$ 633.40
5	REAR BUMPER TOWING COVER <i>Rehd</i>	1	\$ 80.00	\$ 80.00
6	REAR BUMPER CENTRE BRACKET <i>Rehd</i>	1	\$ 303.41	\$ 303.41
7	REAR BUMPER REFLECTOR <i>New</i>	2	\$ 130.50	\$ 261.00
8	REAR BUMPER REINFORCEMENT <i>Rehd</i>	1	\$ 655.20	\$ 655.20
9	REAR BUMPER REVERSE SENSOR <i>Rehd</i>	2	\$ 320.20	\$ 640.40
10	END PANEL <i>Rehd</i>	1	\$ 885.00	\$ 885.00
11	END PANEL INNER GARNISH <i>Rehd</i>	1	\$ 225.50	\$ 225.50

385741

3471.66

TOTAL PRICE	\$ 5,841.41
LESS 10%	\$ 584.14
SUB TOTAL PRICE	\$ 5,257.27

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>Bent</i>	1	\$ 50.00	\$ 50.00
2	REAR BUMPER CLIP (SET) <i>Rehd</i>	1	\$ 30.00	\$ 30.00
3	REAR END PANEL TOP GARNISH CLIPS <i>Rehd</i>	1	\$ 30.00	\$ 30.00
4	REAR END PANEL INSULATION SEAL <i>Rehd</i>	1	\$ 150.00	\$ 150.00

5	REVERSE CAMERA	1	\$ 550.00	\$ 550.00
---	----------------	---	-----------	-----------

380

460

TOTAL \$ 810.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,000.00	400	
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,000.00	400	
3	TUFF COAT	\$ 250.00	40	
4	WIRING CHECK	\$ 80.00	30	
5	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50	
6	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	50	

TOTAL \$2,490.00

970

ESTIMATE REPORT

TOTAL PARTS COST : \$ 6,067.27
TOTAL LABOUR COST : \$ 2,490.00
TOTAL REPAIR COST : \$ 8,557.27

APPROVED DETAILS

EXCESS :
NO. OF WORKING DAYS :
RE-SURVEY :
PART BY PART OR LUMP SUM :
DATE & TIME OF SURVEY :
SURVEYED BY :
CONTACT NUMBER :
FAX NUMBER :

Adrian Lj
L/S 10/03/21

04 Days
Total: 4901.66

L/S: 3.9K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

3.9K