



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name	KCV12557/ISMANI BIN KASIMI
	Reg No/Reg Date	SMR574L / 17/12/201
	Date In/Mileage	10/03/2021/ 0
	Chassis No	GF7W0600199
	Engine No	4J11AA2736
	Make/Model	MIT/19MY OUTLANDER 2.0 MODERN(995)
	Colour/Trim	U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
KAX00008	Credit	10/03/2021/ 16:22	QUK	282 / Kevin Leong	63840		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE FRT BUMPER, BOTH FRT FENDER, SUPPORT, BONNET & AFFECTED AREA REPAIR ON BOTH FRT DOOR							3150.00
E PNT98000 PAINT WORK ON FRT BUMPER, BONNET, BOTH FRT FENDER & BOTH FRT DOOR							2100.00
E PNT88000 REMOVE & INSTALL RADIATOR, CONDENSER FOR FACILITATE REPAIR							120.00
A 55900099 TO TOP UP AIRCON GAS							80.00
M SUNDRY PERFORM RUST PREVENTION							80.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM							30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST							120.00
M SUNDRY TO SUPPLY FRT NUMBER PLATE WITH FRAME							50.00
M SUNDRY SUNDRIES							50.00
M	HEADLAMP ASSY,LH			1.00	1948.00	23.00	1499.96
M	HEADLAMP ASSY,RH			1.00	1948.00	23.00	1499.96
M	HORN,THEFT PROTECTION			1.00	92.00	23.00	70.84
M	GARNISH,FR BUMPER SIDE			1.00	220.00	23.00	169.40
M	GARNISH,FR BUMPER SIDE			1.00	220.00	23.00	169.40
M	COVER,FR BUMPER			1.00	361.00	23.00	277.97
M	EXTENSION,FR BUMPER			1.00	517.00	23.00	398.09
M	BRACKET,FR BUMPER SIDE,LH			1.00	18.00	23.00	13.86
M	BRACKET,FR BUMPER SIDE,RH			1.00	18.00	23.00	13.86
M	BAR,FR BUMPER GUARD			1.00	130.00	23.00	100.10
M	REINFORCEMENT,FR BUMPER			1.00	493.00	23.00	379.61
M	REINFORCEMENT,FR BUMPER			1.00	135.00	23.00	103.95
M	REINFORCEMENT,FR BMPR SIDE			1.00	22.00	23.00	16.94

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	<table> <tr> <td>Cust No/Name</td><td>KCV12557/ISMANI BIN KASIMI</td></tr> <tr> <td>Reg No/Reg Date</td><td>SMR574L / 17/12/201</td></tr> <tr> <td>Date In/Mileage</td><td>10/03/2021/ 0</td></tr> <tr> <td>Chassis No</td><td>GF7W0600199</td></tr> <tr> <td>Engine No</td><td>4J11AA2736</td></tr> <tr> <td>Make/Model</td><td>MIT/19MY OUTLANDER 2.0 MODERN(995)</td></tr> <tr> <td>Colour/Trim</td><td>U01 TITANIUM GREY M/ BK BLACK</td></tr> </table>	Cust No/Name	KCV12557/ISMANI BIN KASIMI	Reg No/Reg Date	SMR574L / 17/12/201	Date In/Mileage	10/03/2021/ 0	Chassis No	GF7W0600199	Engine No	4J11AA2736	Make/Model	MIT/19MY OUTLANDER 2.0 MODERN(995)	Colour/Trim	U01 TITANIUM GREY M/ BK BLACK
Cust No/Name	KCV12557/ISMANI BIN KASIMI														
Reg No/Reg Date	SMR574L / 17/12/201														
Date In/Mileage	10/03/2021/ 0														
Chassis No	GF7W0600199														
Engine No	4J11AA2736														
Make/Model	MIT/19MY OUTLANDER 2.0 MODERN(995)														
Colour/Trim	U01 TITANIUM GREY M/ BK BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	10/03/2021/ 16:22	QUK	282 / Kevin Leong	63840

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M REINF,FR BUMPER SIDE,RH	1.00	69.00	23.00	53.13
M REINF,FR BUMPER SIDE,LH	1.00	60.00	23.00	46.20
M COVER,HEADLAMP SUPT PANEL	1.00	50.00	23.00	38.50
M GRILLE ASSY,RADIATOR	1.00	550.00	23.00	423.50
M COVER,FR BUMPER	1.00	25.00	23.00	19.25
M BRACKET,RADIATOR GRILLE,LH	1.00	13.00	23.00	10.01
M BRACKET,RADIATOR GRILLE,RH	1.00	17.00	23.00	13.09
M HOOD	1.00	980.00	23.00	754.60
M WEATHERSTRIP,HOOD	1.00	41.00	23.00	31.57
M WEATHERSTRIP,HOOD	1.00	40.00	23.00	30.80
M HINGE,HOOD,LH	1.00	68.00	23.00	52.36
M HINGE,HOOD,RH	1.00	68.00	23.00	52.36
M LATCH,HOOD	1.00	76.00	23.00	58.52
M FENDER,FR LH	1.00	622.00	23.00	478.94
M FENDER,FR RH	1.00	622.00	23.00	478.94
M PANEL,HEADLAMP SUPPORT,UPR	1.00	183.00	23.00	140.91
M PNL,HEADLAMP SUPT,UPR LH	1.00	58.00	23.00	44.66
M PNL,HEADLAMP SUPT,UPR RH	1.00	58.00	23.00	44.66
M PANEL,HEADLAMP SUPPORT,LWR	1.00	107.00	23.00	82.39
M SHIELD,FR WHEELHOUSE,LH	1.00	164.00	23.00	126.28
M SHIELD,FR WHEELHOUSE,RH	1.00	164.00	23.00	126.28
M GARNISH,FR BUMPER SIDE	1.00	112.00	23.00	86.24

Confirm & accepted by

7% GST on	13687.13	13,687.13
		958.10
Total Payable		14,645.23

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.