



CLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD  
PANDAN GARDENS CUSTOMER SERVICE CENTRE  
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Reg No : 199405410K

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
LE MY DIEP BLK 490 JURONG WEST AVENUE 1 #06-07 SINGAPORE 640490 Contact No Mobile: 90014232	Cust No/Name /LE MY DIEP Reg No/Reg Date SMF7496X / 23/11/201 Date In/Mileage / 0 Chassis No KNAF3416MK5020921 Engine No G4FGJH709505 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim BBL HORIZON BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00081	Cash	10/03/2021/ 14:07	BLC	442 / CocoLu	30275		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW FRT <sup>1</sup> BUMPER, FRT <sup>1</sup> FENDER RH, FRT SUPPORT PANEL				2 X 410			870 1200.00
E PNT98000 SPRAY PAINT FOR FRT <sup>1</sup> BUMPER, FRT <sup>1</sup> FENDER RH				1 X 350			700.00
B WHEELALIGNMENT To Conduct Computerize Full Wheel Alignment							120.00
A 90000001 CHECK WIRING & ELECTRICAL SYSTEM							30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST							120.00
M SUNDRY Sundry							20.00
B WHEELALIGNMENT To Conduct Computerize Full Wheel Alignment							120.00
M SUNDRY TRANSFER FRT RIGHT RIM							30.00
M SUNDRY SUPPLY FRT RIGHT RIM							360.00
M COVER-FR BUMPER				1.00	633.00	00.00	633.00
M MOULDING-FRONT BUMPER, RH				1.00	36.00	00.00	36.00
M GRILLE-FRONT BUMPER				1.00	262.00	00.00	262.00
M BRACKET-FR BUMPER UPR SIDE MTG				1.00	22.00	00.00	22.00
M PANEL-FENDER, RH				1.00	430.00	00.00	430.00
M CARRIER ASSY-FRONT END MODULE				1.00	675.00	00.00	675.00
M LAMP ASSY-HEAD, RH				1.00	1219.00	00.00	1219.00
M GUARD ASSY-FRONT WHEEL, RH				1.00	95.00	00.00	95.00

Estimate

Steve CLKK)  
10/3/21, 2:30pm  
DD- NM AL  
EXPERI-?  
P/P

LKK Auto Consultants hence notify  
the Repairer of the following:  
• To resurvey before/after spray painting

# Estimate

Steve CLKK  
10/3/21, 2:30pm

DD-NM AL  
EXPIR-?  
P/P

My BLC SK  
5 days

Confirm & accepted by  
• This estimate is on a "Without Prejudice" basis  
• No illegal modification(s) is allowed  
• Supplementary item(s) must be re-quoted and is subject to final approval from Insurance Company

Acknowledged By Repairer

Authorized signatory and company stamp

Nett 6,072.00  
425.04  
Total Payable 6,497.04

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.