



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
LE MY DIEP	Cust No/Name /LE MY DIEP
BLK 490 JURONG WEST AVENUE 1	Reg No/Reg Date SMF7496X / 23/11/201
#06-07	Date In/Mileage / 0
SINGAPORE 640490	Chassis No KNAF3416MK5020921
Contact No Mobile: 90014232	Engine No G4FGJH709505
	Make/Model KIA/CERATO 1.6 A EX G333
	Colour/Trim BBL HORIZON BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00081	Cash	10/03/2021/ 14:07	BLC	442 / CocoLu	30275		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000				2 x 490			800 1200.00
RENEW FRT ¹ BUMPER, FRT ¹ FENDER RH, FRT SUPPORT PANEL							700.00
E PNT98000				1 x 350			120.00
SPRAY PAINT FOR FRT ¹ BUMPER, FRT ¹ FENDER RH							30.00
B WHEELALIGNMENT							120.00
To Conduct Computerize Full Wheel Alignment							30.00
A 90000001							120.00
CHECK WIRING & ELECTRICAL SYSTEM							20.00
A 10028901							120.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST							20.00
USING HI-SCAN PRO TEST							120.00
M SUNDRY							30.00
Sundry							360.00
B WHEELALIGNMENT							633.00
To Conduct Computerize Full Wheel Alignment							36.00
M SUNDRY							262.00
TRANSFER FRT RIGHT RIM							22.00
M SUNDRY							430.00
SUPPLY FRT RIGHT RIM				1.00	633.00	00.00	675.00
M COVER-FR BUMPER				1.00	36.00	00.00	1219.00
M MOULDING-FRONT BUMPER,RH				1.00	262.00	00.00	95.00
M GRILLE-FRONT BUMPER				1.00	22.00	00.00	
M BRACKET-FR BUMPER UPR SIDE MTG				1.00	430.00	00.00	
M PANEL-FENDER,RH				1.00	675.00	00.00	
M CARRIER ASSY-FRONT END MODULE				1.00	1219.00	00.00	
M LAMP ASSY-HEAD,RH				1.00	95.00	00.00	
M GUARD ASSY-FRONT WHEEL,RH							

Estimate

Steve CLKK
10/3/21, 2:30pm
OO- NM AL
Excess - ?
P/P

Estimate

Steve CLKK
10/3/21, 2:30pm
OO- NM AL
EXCIS - ?
PIP

Confirm & accepted by

My RL SN
5 days

7% GST on
Total Payable

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.