



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GW 3131G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BOOT LID	NOT NECESSARY	1,742.00	-
1	REAR BOOT LID EMBLEM LOGO	NOT NECESSARY	66.40	-
1	REAR BOOT LID NV350 LOGO	NOT NECESSARY	101.30	-
1	REAR BUMPER	DEFORMED	667.20	667.20
10	REAR BUMPER CLIP @\$6.50	NECESSARY	65.00	30.00
2	REAR BUMPER SIDE RETAINER @\$18.10	O/S NECESSARY	36.20	18.10
1	REAR BUMPER REVERSE SENSOR	NOT NECESSARY	350.00	-
1	REAR R/H TAILLAMP	CRACKED	224.80	224.80
2	REAR R/H TAILLAMP CLIP @\$8.00	NECESSARY	16.00	8.00
1	REAR R/H TAILLAMP PANEL	TO REPAIR SEE LABOUR	504.00	-
	LESS 10% DISCOUNT		-	-94.81
			3,772.90	853.29
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REAR BOOT LID 70KM/H STICKER (SN)	NOT NECESSARY	30.00	-
1	REAR BOOT LID 8PAX STICKER (SN)	NOT NECESSARY	25.00	-
1	REAR BOOT LID NUMBER PLATE (SN)	NOT NECESSARY	50.00	-
1	GUM (SN)	NOT NECESSARY	50.00	-
			155.00	-
<b><u>LABOUR</u></b>				
	TO REMOVE & REFIT REAR WINDSCREEN.	NOT NECESSARY	120.00	-
	TO REMOVE & REFIT REVERSE SENSOR.		100.00	50.00
	TO CHECK WIRING.		100.00	30.00
	TUFF KOTE.		150.00	50.00
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR R/H TAILLAMP PANEL.		800.00	400.00
	SPRAY PAINTING.		800.00	500.00
			2,070.00	1,030.00
<b>GRAND TOTAL</b>			<b>5,997.90</b>	<b>1,883.29</b>



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,500.00
---	--	--	----------

Report Ref No. CS/AGI21003180/Atd3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.