

LKW AUTO SERVICES

23 HUME AVENUE #05-02 HUME PARK 2 SINGAPORE 598729

EMAIL: lkw.claims@gmail.com

CO. REG. NO: 53401175J

ESTIMATE

Power K RSR contractor.

Not Authorised
11 Rmg @ 4400/h
Penny After Paint
5 days

11/3/21

AM11.00 Date: 10/03/2021

QUANTITY	PARTICULARS	AMOUNT (S)
RE: GBD 6822K Nissan NV350		
1pc	Tailgate lock ✓ 310.60	354.70
1pc	Rear tailgate 1742.00	1998.30
3pc	Tailgate Bump filter 269.50	539.00
1pc	Tailgate outer chrome mouldings. wrap	183.60
1pc	Tailgate weatherstrips. 206.80 X NN	206.80
1pc	Tailgate inner board board. ✓	128.70
1pc	Tailgate lock cover panel B1 ✓	38.90
1pc	Tailgate rear logo (NV350) ✓	62.80
1pc	Tailgate emblem ✓	68.20
1pc	Tailgate emblem (NV350) ✓	51.80
1pc	Rear bumper ✓ 600.50	729.30
1pc	Rear bumper bracket R X	286.50
10pc	Rear bumper cap @ 420	4200.00
1pc	Rear bumper retainer ✓	46.80
222	Tail lamp NLS 4 224.80 @ 286.30	572.60
1pc	End panel B1 ✓	293.70
1pc	Floor board moulding ✓	98.50
LKK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary items must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Mr 302N S/N 60.00 Date: Mr 402N S/N 55.00 Reverse Sensor. 2002N S/N 230.00 Straker (70km/h) 122N S/N 25.00		
Windscreen After Seal Windscreen Sealant		

DILLARD, Anne M., U.S. Industries

DILLARD, Anne M., U.S. Industries

[illegible]