

iShare Auto Pte. Ltd.

Co. Reg No: 201939376R

8 Kaki Bukit Avenue 4

#08-09 Premier @ Kaki Bukit

Singapore 415875

Tel: 6341 6789 Fax: 6341 6778

Email: ishareauto@gmail.com



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey after spray painting
- Resurvey must be done during resurvey
- All prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to approval from Insurance Company

DATE: 15.03.21

Acknowledged by Repairer

Signature:

Date:

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **SLQ1201Z**
MODEL : **HONDA CIVIC**
DATE OF ACCIDENT : 06.03.21
TIME OF ACCIDENT : 19:45HRS

MRHFC5650H7000180

Jasper.

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Rehnd</i>	1	\$ 674.60	\$ 674.60
2	FRONT BUMPER FOGLAMP COVER GARNISH LH <i>new</i>	1	\$ 43.10	\$ 43.10
3	FRONT BUMPER RETAINER <i>LH New</i>	2	\$ 33.60	\$ 67.20
4	FRONT FENDER LH <i>Dented</i>	1	\$ 480.40	\$ 480.40
5	FRONT FENDER SIGNAL LAMP LH <i>at</i>	1	\$ 49.60	\$ 49.60
6	FRONT FENDER INNER SPONGE LH <i>new</i>	1	\$ 76.40	\$ 76.40
7	FRONT FENDER COWLING LH <i>for</i>	1	\$ 132.10	\$ 132.10
8	HEADLAMP (LED) LH <i>and d</i>	1	\$ 894.90	\$ 894.90
9	HEADLAMP LOWER BRACKET LH <i>new</i>	1	\$ 48.30	\$ 48.30
10	HEADLAMP TOP MOULDING (BLACK) LH <i>new</i>	1	\$ 144.20	\$ 144.20
11	RESONATOR BOX <i>new</i>	1	\$ 104.80	\$ 104.80
12	FRONT GRILLE <i>new</i>	1	\$ 171.20	\$ 171.20
13	FRONT GRILLE LOGO <i>new</i>	1	\$ 38.40	\$ 38.40
14	FRONT GRILLE CHROME	1	\$ 130.40	\$ 130.40
15	FRONT WHEEL SPORT RIM LH <i>at</i>	1	\$ 769.20	\$ 769.20
16	FRONT ABS SENSOR RH	1	\$ 149.20	\$ 149.20
17	FRONT SHOCK ABSORBER LH <i>new</i>	1	\$ 368.20	\$ 368.20
18	FRONT KNUCK ARM LH	1	\$ 284.40	\$ 284.40
19	FRONT LOWER ARM LH	1	\$ 439.30	\$ 439.30
20	FRONT DOOR SIDE MIRROR LH <i>Dented</i>	1	\$ 596.80	\$ 596.80
21	SIDE SKIRT LH <i>Rehnd</i>	1	\$ 369.40	\$ 369.40

4000.60

3200.48

TOTAL PRICE \$ 6,032.10
LESS 20% \$ 1,206.42
SUB TOTAL PRICE \$ 4,825.68

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT NUMBER PLATE <i>new</i>	1	\$ 80.00	\$ 80.00

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLQ1201Z**
 MODEL : **HONDA CIVIC**
 DATE OF ACCIDENT : 06.03.21
 TIME OF ACCIDENT : 19:45HRS

2	FRONT BUMPER CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	30
3	FRONT BUMPER FOGLAMP COVER GARNISH CLIP LH (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	x
4	FRONT FENDER INNER COWLING CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	30
5	FRONT GRILLE CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	x
6	FRONT SUPPORT PANEL TOP GARNISH CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	x
7	SIDE SKIRT CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	30
8	FRONT WHEEL TYRE RH <i>best affect</i>	1	\$ 650.00	\$ 650.00	400 200
9	BRAKE OIL <i>new</i>	1	\$ 30.00	\$ 30.00	x

290

TOTAL \$ 1,160.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,800.00	600
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,800.00	800 1000
3	WIRING CHECK	\$ 250.00	30
4	REFOCUS HEADLAMP BEAM	\$ 80.00	x
5	REMOVE & REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$ 350.00	x
6	REMOVE AND REFIX FRONT UNDERCARRIAGE	\$ 650.00	x
7	FOUR WHEEL ALIGNMENT	\$ 120.00	80
8	CONDUCT WATER LEAKAGE TEST	\$ 120.00	x
9	RESET ABS LIGHT	\$ 350.00	x
10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x

TOTAL \$ 5,700.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 5,985.68
 TOTAL LABOUR COST : \$ 5,700.00
 TOTAL REPAIR COST : \$ 11,685.68

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
 PARTS PRICES ARE SUBJECT TO CHANGES.

Adrian Lj
h/s 16/03/21
07 Days
total: 5200.48
h/s: 4.1K

1710