

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 10-Mar-21

INSURANCE: China Taiping

MODEL: TOYOTA PRIUS

VEHICLE NO.: SHC1528C

DESCRIPTION	QTY	LIST PRICE	AMOUNT
BONNET <i>1st</i>	1	\$950.50	\$950.50
BONNET RUBBER <i>HH</i>	1	\$35.50	\$35.50
BONNET LOCK <i>HH</i>	1	\$132.60	\$132.60
FRONT BUMPER COVER <i>turn</i>	1	\$499.90	\$499.90
FRONT BUMPER REINFORCEMENT <i>1st</i>	1	\$696.40	\$696.40
FRONT BUMPER REINFORCEMENT ABSORBER <i>crack</i>	1	\$115.70	\$115.70
FRONT BUMPER LOWER REINFORCEMENT <i>HH</i>	1	\$364.20	\$364.20
FRONT BUMPER LOWER REINFORCEMENT BRACKET <i>HH</i>	1	\$330.00	\$330.00
FRONT SIDE MEMBER REINFORCEMENT PANEL (LH/RH) <i>HH</i>	2	\$ 320.70	\$641.40
FRONT SIDE MEMBER SIDE COVER <i>HH</i>	2	\$ 172.50	\$345.00
FRONT BUMPER SPONGE <i>turn</i>	1	\$78.80	\$78.80
FRONT BUMPER LOWER GRILLE <i>damaged / cut</i>	1	\$166.90	\$166.90
LAMP ASSY, FOG, LH <i>broken</i>	1	\$920.00	\$920.00
FRONT BUMPER SIDE RETAINER <i>1/2 dislodged / broken</i>	1	\$77.00	\$77.00
FRONT LOWER PANEL <i>HH</i>	1	\$320.65	\$320.65
FRONT LOWER SIDE RAIL (LH) <i>HH</i>	1	\$230.80	\$230.80
COVER, FRONT BUMPER HOLE, LH <i>dislodged</i>	1	\$28.38	\$28.38
UNIT ASSY, HEADLAMP, LH (LED) <i>broken</i>	1	\$3,455.00	\$3,455.00
HEAD LAMP PANEL (LH) <i>HH</i>	1	\$240.10	\$240.10
TOP PANEL CENTRE <i>1st HH</i>	1	\$364.98	\$364.98
TOP PANEL SIDE <i>1st</i>	1	\$145.90	\$145.90
RADIATOR ASSY <i>HH</i>	1	\$1,841.80	\$1,841.80
RADIATOR FAN GRILLE <i>HH</i>	1	\$632.40	\$632.40
GUIDE RADIATOR AIR NO.3 <i>HH</i>	1	\$299.70	\$299.70
COOLANT <i>HH</i>	1	\$45.00	\$45.00
DEFLECTOR, RADIATOR SIDE, LH <i>HH</i>	1	\$83.50	\$83.50
STAY, RADIATOR SUPPORT, LH <i>HH</i>	1	\$65.70	\$65.70
RADIATOR FAN BLADE (LH) <i>HH</i>	1	\$233.10	\$233.10
RADIATOR FAN MOTOR (LH) <i>HH</i>	1	\$543.70	\$543.70
RADIATOR FAN COWLING (LH) <i>HH</i>	1	\$451.30	\$451.30
CONDENSER ASSY, W/RECEIVER <i>HH</i>	1	\$1,336.60	\$1,336.60
FENDER SUB-ASSY, FRONT LH <i>Revised</i>	1	\$945.30	\$945.30
FRONT FENDER SHIELD <i>SL</i>	1	\$38.00	\$38.00
FRONT FENDER SHIELD CLIP <i>HH</i>	1	\$14.90	\$14.90
FRONT FENDER HYBRID EMBLEM, LH <i>rec</i>	1	\$86.50	\$86.50
BRACKET, FRONT SIDE PANEL, LH <i>HH</i>	1	\$86.30	\$86.30
FRONT WHEEL RIM <i>distorted</i>	1	\$1,570.55	\$1,570.55
FRONT WHEEL RIM CAP <i>dislodged / broken</i>	1	\$189.60	\$189.60
FRONT WHEEL HUB CAP <i>HH</i>	1	\$177.70	\$177.70
FRONT WHEEL HUB BEARING <i>Done</i>	1	\$560.10	\$560.10
FRONT SUSPENSION LOWER ARM (LH) <i>Done</i>	1	\$637.50	\$637.50

2637.60

FRONT SHOCK ABSORBER (LH) <i>2 distm</i>	1	\$401.80	\$401.80	<i>✓</i>
KNUCKLE, STEERING, LH <i>2 distm</i>	1	\$580.80	\$580.80	<i>✓</i>
JOINT ASSY, LOWER BALL, FRONT (LH) <i>2 H</i>	1	\$199.98	\$199.98	<i>✓</i>
END SUB-ASSY, TIE ROD, LH <i>2 H</i>	1	\$159.30	\$159.30	<i>✓</i>
SUB TOTAL			\$20,202.24	
LESS 20% <i>25%</i>			\$4,040.45	
DISCOUNTED TOTAL			\$16,161.79	
FRONT NO. PLATE <i>H</i>	SN 1	\$25.00	\$25.00	<i>X</i>
FRONT NO. PLATE TRIM COVER <i>H</i>	SN 1	\$30.00	\$30.00	<i>X</i>
FRONT NO. PLATE GARNISH <i>H</i>	SN 1	\$99.00	\$99.00	<i>X</i>
FRONT BUMPER LOGO <i>H</i> <i>List</i>	SN 1	\$87.10	\$87.10	<i>✓ List</i>
FRONT TYRE (LH) <i>SN</i>	SN 1	\$216.00	\$216.00	<i>X</i>
SUB TOTAL			\$457.10	
Labour Charge				
Panel Beating	1	\$1,400.00	\$1,400.00	<i>700/-</i>
Spray Painting Charge	1	\$1,200.00	\$1,200.00	<i>600/-</i>
Wiring Charge	1	\$120.00	\$120.00	<i>30/-</i>
Tuff Kote	1	\$120.00	\$120.00	<i>40/-</i>
Towing Charge	1	\$80.00	\$80.00	<i>H</i>
Four Wheel Alignment	1	\$120.00	\$120.00	<i>60/-</i>
Remove/Refix Undercarriage (Frt)	1	\$400.00	\$400.00	<i>150/-</i>
Re-set Frt ABS System	1	\$200.00	\$200.00	<i>H</i>
Remove/Refix Radiator	1	\$90.00	\$90.00	<i>H</i>
Remove/Refix Aircon & Refill Gas	1	\$130.00	\$130.00	<i>H</i>
Remove/Refix Fuse Box	1	\$120.00	\$120.00	<i>H</i>
Diagnostic & Resetting To Erase Fault Code	1	\$550.00	\$550.00	<i>150/-</i>
TOTAL LABOUR			\$4,530.00	
ESTIMATE TOTAL			\$21,148.89	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

11376.33
8532.24

1730.00

11/03/2021 @ 0915hrs

H/A Authorised

2/5 hrs 7 days

[Signature]

LKK Auto

[Signature]

10262.24

Supp 2818.65

13080.85

1/5 11,700/-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

BIFROST AUTO PTE LTD

Supplementary ESTIMATE

DATE: 11-Mar-21

INSURANCE: Chine Teiping

MODEL: TOYOTA PRIUS

VEHICLE NO.: SHC 1528C (S)

DESCRIPTION	QTY	LIST PRICE	AMOUNT
HEADLAMP ECU <i>money broker</i>	1	\$682.60	\$682.60
SUB TOTAL			\$682.60
LESS 20% 25%			\$136.52
DISCOUNTED TOTAL			\$546.08

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

S. Yan
2kk Auto

511.95

REPAIR ESTIMATE

INSURANCE: China Taiping

VEHICLE NO.: SHC 1528 C

438.00
2637.60

3075.60

25% 2306.70

1 year

2 Kk AaBb