



Address: 60 JALAN LAM HUAT, CARROS CENTRE #05-68 S737896
HP: 98888885

10/3/2021

SGJ82C

BENTLEY BENTAYGA

Chassis No:

CLASSIS NO.				
No.	Description	Unit	Unit Price	Amount
	Parts Replacement:			
1	REAR BUMPER / <i>pet.</i>	1	\$ 16,124.50	\$ 16,124.50
2	REAR BUMPER LOWER <i>x</i>	1	\$ 8,142.00	\$ 8,142.00
3	REAR BUMPER DIFFUSER / <i>chy</i>	1	\$ 5,814.00	\$ 5,814.00
4	REAR BUMPER REFLECTOR LH <i>x 11</i>	1	\$ 354.00	\$ 354.00
5	REAR BUMPER LOWER LAMP <i>11x</i>	1	\$ 1,159.00	\$ 1,159.00
6	REAR BUMPER CENTRE BRACKET <i>11x</i>	1	\$ 512.00	\$ 512.00
7	REAR BUMPER CHROME (CENTRE) / <i>GRV</i>	1	\$ 698.00	\$ 698.00
8	REAR BUMPER CHROME (SIDE) / <i>H/SCH</i>	<i>1/2</i>	\$ 398.00	\$ 796.00
9	REAR BUMPER TOWING COVER <i>x 11</i>	1	\$ 112.00	\$ 112.00
10	REAR BUMPER REINFORCEMENT <i>Rx</i>	1	\$ 3,215.00	\$ 3,215.00
11	REAR BUMPER SIDE RETAINER <i>11x</i>	2	\$ 290.00	\$ 580.00
12	REAR BUMPER REVERSE SENSOR / <i>H/SCH</i>	<i>1/2</i>	\$ 487.00	\$ 1,948.00
13	TAILGATE <i>x 11</i>	1	\$ 24,879.00	\$ 24,879.00
14	TAILGATE LOGO <i>← APC - 11x</i>	1	\$ 321.00	\$ 321.00
15	TAILGATE OUTER CHROME MOULDING <i>x 11</i>	1	\$ 741.00	\$ 741.00
16	TAILGATE WEATHERSTRIPE <i>x 11</i>	1	\$ 487.00	\$ 487.00
17	TAILGATE LOCK <i>x 11</i>	1	\$ 1,025.00	\$ 1,025.00
18	TAILGATE WINDSCREEN MOULDING (SET) <i>x 11</i>	1	\$ 589.00	\$ 589.00
19	REAR END PANEL <i>x R</i>	1	\$ 3,587.00	\$ 3,587.00
20	REAR END PANEL TOP GARNISH <i>x 11</i>	1	\$ 758.00	\$ 758.00
21	REAR EXHAUST CHROME PIPE <i>x 11</i>	2	\$ 1,015.00	\$ 2,030.00
22	REAR EXHAUST PIPE <i>x 11</i>	1	\$ 12,874.00	\$ 12,874.00
23	REAR EXHAUST MOUNTING <i>x 11</i>	2	\$ 68.00	\$ 136.00
	TOTAL PART			\$ 86,881.50
	LIST DOWN	0%	<i>10%</i>	\$ -
	AFTER LIST DOWN			\$ 86,881.50
	S/N			
1	REAR BUMPER CLIP	1	\$ 50.00	\$ 50.00
2	TAILGATE WINDSCREEN SEALANT	1	\$ 150.00	\$ 150.00
3	TAILGATE WINDSCREEN INNER SEAL	1	\$ 150.00	\$ 150.00
4	TAILGATE OUTER MOULDING CLIPS SET	1	\$ 80.00	\$ 80.00
5	TAILGATE INNER TRIM BOARD CLIPS SET	1	\$ 50.00	\$ 50.00
6	REAR END PANEL SEALANT	1	\$ 120.00	\$ 120.00
7	REAR END PANEL TOP GARNISH CLIP	1	\$ 30.00	\$ 30.00
	TOTAL SPECIAL NETT			\$ 630.00
	Labour to:			
1	REMOVE AND REFIT REAR WINDSCREEN GLASS	1	\$ 150.00	\$ 150.00
2	REMOVE AND REFIT REAR SEAT, UPHOLTERY	1	\$ 300.00	\$ 300.00

3	REMOVE AND REFIT REAR REVERSE SENSOR	1	\$ 120.00	\$ 120.00
4	✓ REMOVE AND REFIT REAR EXHAUST SYSTEM	1	\$ 150.00	\$ 150.00
5	REMOVE AND REFIT TAILGATE MECHANISM	1	\$ 150.00	\$ 150.00
6	TUFF COAT	1	\$ 150.00	\$ 150.00
7	PANEL BEATING ON AFFECTED AREA	1	\$ 1,500.00	\$ 1,500.00
8	SPRAY ON AFFECTED AREA	1	\$ 1,500.00	\$ 1,500.00
				\$ 4,020.00
			Parts Replacement Amount	\$ 87,511.50
			Total Amount for Labour	\$ 4,020.00
			Total Amount	\$ 91,531.50

Repair day - 3 days
PIP @ 20402.12

before paint photo

Sun Pinc LKK
03/05/2021

(Finalize with Steve)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Cecilia

9-2146903

102

9-1932212

S.N - 30

L - 1050

20402.12