

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC4/III21003196/KBA3Q2

Date:

07/10/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

D19MFL0005549_01

Claimant Vehicle No : YN108D**Insured Vehicle No :**

GBH5721D

Date of Loss: 23/02/2021

Nature of Claim:

TP

Claim No:

MFL2021D0001008

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **YN108D**

Make & Model: MITSUBISHI CANTER, 3.0 D FEB21ER3SDEB (CBU) (M)

Engine No:

4P10D80048

Reg. Date: 20/09/2019 (Man. Year: 2019)

Chassis No:

FEB21EA30326

Colour: White

Odometer:

25201 km

Engine Capacity: 2998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size:

195/65 R15 (D)

Front Left Side: Dunlop 8 mm

Rear Left Side:

Dunlop 8/8 mm

Front Right Side: Dunlop 8 mm

Rear Right Side:

Dunlop 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,761.54	4,039.44	722.10	15.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,150.00	1,740.00	410.00	19.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,911.54	5,779.44	1,132.10	16.38
Approved Total (Overridden) (S\$)		4,650.00		

(S\$)	6,911.54	4,650.00	2,261.54	32.72
+ GST 7.00/7.00% (S\$)	483.81	325.50	158.31	32.72
Nett Amount (S\$)	7,395.35	4,975.50	2,419.85	32.72
+ Car Rental (14.0 x S\$100.00/day) (S\$)		1,400.00		
Nett Liability (S\$)		6,375.50		
Global Sum Settlement (S\$)		6,300.00		

INSPECTION

Date of Assignment: 11/03/2021

Date Inspected: 11/03/2021

Inspected At:

Bifrost Auto Pte Ltd (sin Ming) (HQ)
 Blk 9 Sector C, #01-42 Sin Ming Industrial Estate
 Singapore 575644

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 07 Jul 2021)	
Parts:	N/A	MITSUBISHI CANTER 3.0 D FEB21ER3SDEB (CBU) (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YN108D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE SIDE LOCK(LH)	Bent	68.00 FL	*68.00 FL
2	1		*TAIL GATE STOPPER (LH)	Serviceable	49.67 FL	*- FL
3	1		*TAIL GATE STOPPER BRACKET (LH)	Bent	65.00 FL	*65.00 FL
4	1		*TAIL LAMP (LH)	Broken	194.25 FL	*194.25 FL
5	1		*TAIL GATE FUSO STICKER	Necessary	180.00 FS	*180.00 FS
6	1		*TAIL GATE 60KM/HOUR STICKER	Necessary	15.00 FS	*12.00 FS
7	1		*TAIL GATE 6 PAX STICKER	Necessary	15.00 FS	*12.00 FS
8	1		*SIDE GATE (LH)	Bent	1,500.00 FS	*1,500.00 FS
9	1		*SIDE GATE PARTITION (LH)	Dented	450.00 FS	*450.00 FS
10	1		*SET COMPANY LOGO STICKER	Necessary	300.00 FS	*200.00 FS
11	1		*TAIL GATE	Bent	1,200.00 FS	*1,200.00 FS
12	2		*REAR CABIN COMPARTMENT BRACKET	Distorted (1 PCS ONLY)	160.00 FS	*80.00 FS
13	8		*REAR CABIN COMPARTMENT U BOLTS	Bent (2 PCS ONLY)	640.00 FS	*160.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	4,836.92	4,121.25
- List Item Discount on L Items 20.00/25.00% (S\$)	75.38	81.81
Total Parts (S\$)	4,761.54	4,039.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PUTTY & SPRAY PAINTING	New	700.00	550.00
2	LABOUR CHARGE	New	600.00	540.00
3	TO SPRAY PAINT FRONT CABIN REAR PANEL	New	250.00	200.00
4	LABOUR CHARGES	New	600.00	450.00
Gross Labour Cost (S\$)			2,150.00	1,740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >