

Our Job Ref No : 305455058
Date : 26/02/21

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : NAZ

Vehicle Reg No. : SHC8553H

Date of Accident : 22/02/2021

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- SLH4092Z
##

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

Total for Part-By-Part Repair Cost

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: 20%

Final Lumpsum Repair cost

\$3650.00

3. Estimated normal period for repairs: 4 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and
finalized amount

Signature : [Signature]

Name : JUMANI

Tel : 62148315

Fax : 65468156

Signature : [Signature]

Name : NAZ

Date : 11/3/2021

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	---	N		
3. Survey Fees	--	-		
4. LTA Search Fee	\$7.49 /\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks:

Towing

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Vehicle No.: SHC8553H
 Make : HYUNDAI
 Model : I40
 DOA : 22.02.21

Date : 23/2/2021
 Insurance: NTUC
 MVA : JUMANI
 Admin :

Part No.	Parts Description / Labour	Qty	Unit Price	Amount
	BONNET			\$2,265.90
	BONNET HINGE LH			\$35.70
	BONNET HINGE RH			\$35.70
	FRT BUMPER ASSY			\$1,052.20
	FRT BUMPER BRACKET LH			\$44.60
	FRT BUMPER BRACKET SIDE LH			\$49.20
	HEADLAMP PANEL SUPPORT			\$997.40
	HEADLAMP ASSY LH			\$1,800.00
	FRT FENDER LH			\$663.00
	FRT BUMPER SHIELD LH			\$174.90
	FRT WHEEL HUB CAP			\$217.20
	FRT WHEEL RIM			\$650.60
	HEADLAMP BULB	2		\$57.60
	FRT SHOCK ABSORBER LH			\$684.40
	FRT SHOCK ABSORBER MTG LH			\$217.60
	FRT LOWER ARM SUSPENSION LH			\$595.90
	STG TIE ROD LH			\$186.40
	KUNCKLE ARM LH			\$552.00
				\$10,280.30
	SUB TOTAL		3,732.40	\$10,280.30
	LESS 20%			\$2,056.06
	DISCOUNTED TOTAL		2,985.92	\$8,224.24
	TYRE FRT LH	40% off	\$216.00	\$100.00
	FRT LH FENDER ADVERTISEMENT LOGO			
				\$316.00
	Labour Charge			
	PANEL BEATING			\$900.00
	SPRAYPAINT			\$900.00
	CHECK WIRING			\$50.00
	TUFF KOTE			\$50.00
	ADJUST FOUR WHEEL ALIGNMENT			\$120.00
	REMOVE/REFIX FRT SUSPENSION DAMAGED PARTS			\$120.00
	REMOVE/REFIL AIRCON PARTS AND GAS			\$120.00
	TOTAL LABOUR		4,552.32	\$2,260.00
	ESTIMATE TOTAL		3,641.85	\$10,800.24

NAZUK
 23/2/2021 1600
 LIS
 40.30

CHECK ITEM (HOTO)
 AFTER PAINT (HOTO)

3,650.00

Part No.	Parts Description / Labour	Qty	Unit Price	Amount

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: