

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.
TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com
Business Regn No: 269436/00J

10, Mar 2021

Ergo Insurance Pte Ltd
5 Temasek Boulevard
#04-01 Suntec Tower Five

CDMCG21000452

Not Notified
61 Pp & 6750p
Murray After Paint
14 days

Attn: motor claim dept-3rd party claim

Claiming against your insured vehicle no: XD5818U

Accident involving vehicle no: SMK9800L/XD5818U

DOA: 10/03/2021 At Along Holland Road twds Orchard Nr Moonbeam Bus stop

Dear officer incharge

Re: estimate cost of repair for vehicle no: SMK9800L

To supply--

Description	Qty	Amount
Tailgate <i>818</i>	1	<i>B1</i> 828.00 ✓
Tailgate hinge @192	2	<i>D11</i> 384.00 ✓
Tailgate lock	1	<i>D11</i> 206.00 ✓
Tailgate outer handle-chrome	1	<i>Warp</i> 318.00 ✓
Tailgate-Attrage emblem	1	<i>in</i> 38.00 ✓
Rear fender, Rh n Lh @715	2	<i>Bu</i> 1,430.00 ✓
Taillamp R n L @276	2	<i>Bu</i> 552.00 ✓
Spare tyre panel	1	<i>R</i> 906.00 X
Rear bumper	1	<i>B1</i> 708.00 ✓
Rear bumper enforcement	1	
Rear bumper retainer @42	2	<i>D11</i> 84.00 ✓
Rear bumper reflector @46	2	<i>in</i> 92.00 X
End panel	1	<i>B1</i> 402.00 ✓
End panel top garnish	1	<i>D11</i> 82.00 ✓
Boot weatherstrip	1	<i>D11</i> 168.00 <i>508in 848in</i>
Parts		6,198.00
Parts less 20% <i>10%</i>		1,239.60
		4,958.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

101003214/kv

Vehicle no: SMK9800L

Reverse sensor

To remove/reinstall rear windscreen glass

To remove rear seater, inner garnish, rear speaker board enable repair job carryout.

Reinstall after job done

To apply rust proofing

To remove parts n attachments

Cut n weld damaged panel

Repair/reshape dented areas

Straighten rear chassis where necessary

Replace/align all parts into position

To spray paint-

220.00 200sm

180.00 12cl

250.00 12cl

120.00 ✓

1,800.00 170cl

1,600.00 120cl

9,128.40

10,137.81

威利摩哆
WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.

TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com
Business Regn No: 269436/00J

16,MAR 2021

ERGO Insurance PL

Vehicle no: SMK9800L

Supplementary parts for vehicle no: SMK9800L

To supplied—

1) Spare tyre board

CM \$ 156.90 ✓

Less 10%

\$ 15.69

\$ 141.21

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.

TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com
Business Regn No: 269436/00J

12,MAR 2021

Ergo Insurance Pte Ltd

Vehicle no: SMK9800L

Supplementary parts for vehicle no: SMK9800L

To supplied—

Description		Qty	Amount
Taillamp inner panel @76		2 <i>B7</i>	152.00 ✓
Top trim panel @62		2 <i>R1</i>	124.00 ✓
Parts			276.00
Parts less			27.60
			248.40

Vehicle no: SMK9800L

Supplementary parts for vehicle

To supplied—

Description		Qty	Amount
Taillamp inner panel		2	152
Top trim panel		2	124
Parts			276.00
Parts less			27.60
			248.40

Vehicle no: SMK9800L

Supplementary parts for vehicle

To supplied—

Description		Qty	Amount
Taillamp inner panel		2	152
Top trim panel		2	124
Parts			276.00
Parts less			27.60
			248.40