



Reg. No. 289644/OOC

FIRST MOTOR

Blk 3006 Ubi Road 1 #01-398 Singapore 400306

Tel: 6743 1911, 6744 8333 Fax: 065-6745 8333

E-mail: lionell@singnet.com.sg

E-mail: first_motor_sg@yahoo.com

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

08 MARCH 2021

MODENAS ELEGAN 250

①	TAIL LAMP / Cnt	SCR	#275	220	
②	REAR FENDER (MARB GUARD)		#118	/	
③	NO PLATE / BT		#20	10(SN)	
④	COVER R/H TOP - Cnt		#180	/	
⑤	COVER R/H LOWER - Cnt		#175	/	
⑥	SIDE COVER R/H - Cnt		#275	185	
⑦	EXHUST COVER - Cnt		#115	55	
⑧	PILLION BRACKET X NN		#175	X	
⑨	BRAKE LEVER - Cnt		#65	25	
⑩	BALANCER R/H - Cnt		#35	15	
⑪	FOOTREST R/H X	} NN	#65	X	2 Days
⑫	MIRROR R/H X		#140	X	
⑬	SIGNAL FRONT R/H - CA		#190	148	1176
⑭	FRONT FENDER X NN		#230	X	-10% = 1058.4
⑮	TAIL COVER / Cnt		#95	55	1268.4
⑯	WORKMANSHIP				20% = 1000
	STRIP & Fix Body Parts		#280	200	
⑰	TOWING SERVICE		#60	X NN	
	TOTAL		2493		