


ASSIGNMENT

From _____ Date _____
 Estimated Cost: _____
 OD TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s ATIAN Motoring
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? Yes or No
 GIA / PR Seen: _____ Consistent? Yes or No
 Est. Repairs: 2 days Res: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: 2698R Regn: 04 Mar 2019
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Yamaha YZF-R155 cc 155
 Colour: Black A/C: Insured / Std / NI / NA
 Sp Reading: 7690 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: MH 3RG 4710 KK 093899
 Gen Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 100/80-17
 R: 40/70-17
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or IRC
 Front: _____ Rear: _____
 R/Bal: 5 mm R/Bal: 5 mm
 L/Bal: _____ mm L/Bal: _____ mm
 D.O.A: 8/3/21 D.O.I: 11-03-21
 Survey held at: W/S 5:30pm
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
11/03	Finalized \$613.6 (Red 140.40, 18%)
22/3/21	Guo Qiang re-confirmed LS \$672.10 (Red 1469.90, 18%)

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

22/3/21-Typist

Days Of Repair: 2

Resurvey No. of Trip: 1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Insp (\$

☐

Final Insp (\$

Survey Fee:

Transportation

\$ + RS \$

Photos

Notes

Merimen

\$672.10



9795 7182

UKK Auto Consultants hereby notify the Registrar of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

240

Qty	Description	Unit Price	Total Price
1 pc	Gear Lever / <i>ad.</i>	55.00	
1 pc	Left Signal / <i>cat</i>	30.00	
1 pc	Clutch Lever / <i>BT</i>	18.00	
1 pc	Balancer / <i>cat</i>	8.00	
1 pc	Kick Stand / <i>GBT</i>	38.00	
1 pc	Handle Bar / <i>GBT</i>	85.00	
1 pc	Left Rear Side Cover / <i>GA</i>	65.00	
1 pc	Left Side Mirror / <i>cat</i>	55.00	
1 pc	Number Plate Lamp / <i>BT</i>	25.00	
1 pc	Rear Number Plate Reflector / <i>GA</i>	25.00	
	Fork Alignment	120.00	
	Tpt to Idac to Workshop	80.00	
	Labour	<u>150.00</u>	
	Sub Total	754.00	
	7% GST	52.78	
	Total	806.78	

P/P.
After repair photos.

Case Qs ap - 82880282

2 Days

11/3/2021

404
10% 363.6
613.6