

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21003222/EPA3Q2**Date:** 17/05/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900251994
Claimant Vehicle No :	YP2172T	Insured Vehicle No :	SMQ8624D
Date of Loss:	05/03/2021	Nature of Claim:	TP
		Claim No:	5306016244SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YP2172T		
Make & Model:	MITSUBISHI CANTER, 3.0 D FEB21ER4SDEB (CBU) (M)	Engine No:	4P10C18958
Reg. Date:	05/05/2016 (Man. Year: 2016)	Chassis No:	FEB21EA20512
Colour:	White	Odometer:	162404 km
Engine Capacity:	2998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/85 R15	Rear Tyre Size:	195/85 R15
Front Left Side:	Delium 3 mm	Rear Left Side:	Delium 3 mm
Front Right Side:	Delium 3 mm	Rear Right Side:	Delium 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,541.66	294.80	3,246.86	91.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,150.00	710.00	1,440.00	66.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,691.66	1,004.80	4,686.86	82.35
Approved Total (Overridden) (S\$)		800.00		
(S\$)	5,691.66	800.00	4,891.66	85.94
+ GST 8.00/8.00% (S\$)	455.33	64.00	391.33	85.94
Nett Amount (S\$)	6,146.99	864.00	5,282.99	85.94
+ Loss of Use (3.0 x S\$80.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,106.00		

INSPECTION

Date of Assignment:	11/03/2021	
Date Inspected:	24/03/2021	Inspected At: Efficient Motor & Engineering Works Pte Ltd (HQ) 37 Loyang Way Singapore 508734
Estimated Period of Repair:	3.0 days	

Adjuster: CHEN TSUE YEE**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL LAMP RH	Broken	194.22 FL	*194.22 FL
2	1		*REAR NUMBER PLATE LIGHT	Not Necessary	79.85 FL	*- FL
3	1		*SLIDING REAR DOOR RH	Not Necessary	800.00 FS	*- FS
4	1		*SLIDING DOOR GUIDE RH	Not Necessary	500.00 FS	*- FS
5	1		*SLIDING DR LOWER WOOD FRAME RH	Not Necessary	500.00 FS	*- FS
6	1		*SLIDING DR LOCK ASSEMBLY	Not Necessary	90.00 FS	*- FS
7	1		*REAR RH BOX EDGE PROFILE	Not Necessary	500.00 FS	*- FS
8	1		*REAR DOOR RH LOWER HINGE	Bent	120.00 FS	*120.00 FS
9	1		*REAR DOOR RH	Not Necessary	400.00 FS	*- FS
10	1		*REAR DOOR LOWER WOODEN FRAME	Not Necessary	250.00 FS	*- FS
11	1		*REAR NO PLATE	Not Necessary	35.00 FS	*- FS
12	1		*REAR NO PLATE BRACKET	Not Necessary	30.00 FS	*- FS
13	1		*PAN PAC METAL PLATE	Not Necessary	50.00 FS	*- FS
14	1		*60KM/H STICKER	Not Necessary	20.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	3,569.07	314.22
- List Item Discount on L Items 10.00/10.00% (S\$)	27.41	19.42
Total Parts (S\$)	3,541.66	294.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT & ALIGN REPAIR PORTION ,REMOVE & REPLACE DAMAGED PARTS	New	1,000.00	350.00
2	TO APPLY ANTI RUST COAT AND TUFF KOTE REPAIRED AREAS	New	100.00	30.00
3	TO CHECK AND RECTIFY LIGHTING & WIRING	New	50.00	30.00
4	TO SPRAY PAINTING FOR REAR PORTIONS & AFFECTED AREAS	New	1,000.00	300.00
Gross Labour Cost (\$\$)			2,150.00	710.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >