

PLEASE ARRANGE TO SURVEY
VEHICLE AT 30 BUKIT BATOK
CRESCENT (S 658075)

Selamatshahh
CLAIM DEPARTMENT
DID : 66547519
FAX :

Date : 10/03/2021

To : **CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.**
ESTIMATION

Attn : **Motor Claim Department**

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D20MTRENT000086

Accident Date : 06/03/2021

Vehicle No : SLP-4507-C

Make & Model : TOYOTA COROLLA ALTIS 1.6 ELEGANCE (A)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
List Item			
1	REAR BUMPER <i>de</i>	482.00	
2	REAR BUMPER REFLECTOR <i>?</i>	164.00	
2	REAR BUMPER RETAINER <i>re</i>	238.00	
2	REAR BUMPER BRACKET <i>bt</i>	110.00	
1	REAR BUMPER REINFORCEMENT <i>bt</i>	380.00	
2	REAR IMPACT DAMPER <i>?</i>	150.00	
10	REAR BUMPER CLIPS <i>re</i>	50.00	
1	END PANEL <i>bt</i>	581.00	
1	END PANEL TOP GARNISH <i>de</i>	230.00	

Date : 10/03/2021

To : **CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.**
ESTIMATION

Attn : **Motor Claim Department**

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D20MTRENT000086

Accident Date : 06/03/2021

Vehicle No : SLP-4507-C

Make & Model : TOYOTA COROLLA ALTIS 1.6 ELEGANCE (A)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	SPARE TYRE PANEL <i>bu</i> ✓	750.00	
1	SPARE TYRE BOARD <i>X</i>	270.00	
1	SPARE TYRE LOCK NUT <i>R ?</i>	45.00	
1	BOOT LID <i>bt</i> ✓	650.00	
2	BOOT LID HINGE <i>?</i>	170.00	
1	BOOT LID LOGO <i>re</i> ✓	52.00	
1	EMBLEM - COROLLA <i>re</i> ✓	54.00	
1	EMBLEM - ALTIS <i>re</i> ✓	54.00	
1	BOOT LID LOCK <i>bt</i> ✓	380.00	
1	BOOT LID WEATHERSTRIP <i>re</i> ✓	180.00	

Date : 10/03/2021

To : CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D20MTRENT000086

Accident Date : 06/03/2021

Vehicle No : SLP-4507-C

Make & Model : TOYOTA COROLLA ALTIS 1.6 ELEGANCE (A)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
2	BOOT LID LAMP <i>cm ✓</i>	772.00	
2	TAILLAMP <i>cm ✓</i>	772.00	
2	TAILLAMP PANEL <i>bt ✓</i>	206.00	
1	REAR FENDER RH <i>buc ✓</i>	1,050.00	
1	REAR FENDER LH <i>buc ✓</i>	1,050.00	
2	REAR FENDER INNER TRIM RH/LH <i>2 LH-X/RH-de ✓</i>	1,004.00	
2	REAR FENDER AIRVENT <i>?</i>	260.00	
1	REAR EXHAUST SILENCER <i>?</i>	630.00	
2	REAR EXHAUST MOUNTING RUBBER <i>?</i>	76.00	
1	REAR DOOR RH <i>repair</i>	RESTORE	

Date : 10/03/2021

To : **CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.**
ESTIMATION

Attn : **Motor Claim Department**

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D20MTRENT000086

Accident Date : 06/03/2021

Vehicle No : SLP-4507-C

Make & Model : TOYOTA COROLLA ALTIS 1.6 ELEGANCE (A)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	REAR DOOR LH <i>repair</i>	RESTORE	
1	REAR CHASSIS PANEL RH/LH	RESTORE	
1	ROOF SIDE PANEL RH/LH	RESTORE	
Sub Total		10810.00	
Discount 25% On Parts		(2702.50)	
Special Nett Item			
1	REAR NUMBER PLATE <i>bf</i>	35.00	
1	REVERSE SENSOR <i>rw</i>	220.00	
1	WINDSCREEN SEALANT <i>rw</i>	50.00	
1	END PANEL SEALANT <i>rw</i>	50.00	

Date : 10/03/2021

To : **CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.**
ESTIMATION

Attn : **Motor Claim Department**

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D20MTRENT000086

Accident Date : 06/03/2021

Vehicle No : SLP-4507-C

Make & Model : TOYOTA COROLLA ALTIS 1.6 ELEGANCE (A)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	Sub Total	355.00	
	<u>Labour & Misc</u>		
	LABOUR TO FACILITATE REPAIR	1,980.00	1400
	TO RESPRAY AFFECTED AREAS	1,980.00	1600
	TO PULL AND REALIGN REAR CHASSIS PANEL	400.00	300
	TO REMOVE AND TRANSFER BOOT LID COMPONENTS	150.00	80
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	150.00	120
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	50.00	30
	RUST PROOFING	100.00	50

Date : 10/03/2021
 To : CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
ESTIMATION
 Attn : Motor Claim Department FAX :

Owner : ETHOZ Group Ltd
 : SOMPO INSURANCE SINGAPORE PTE. LTD.
 Certificate No : D20MTRENT000086 Accident Date : 06/03/2021
 Vehicle No : SLP-4507-C Make & Model : TOYOTA COROLLA ALTIS 1.6 ELEGANCE (A)
ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	Sub Total	4810.00	

13,272.50

Remarks:

14 days - Lfs - Resing after repair

SUB TOTAL
 GST 7.0 % 929.08
 TOTAL 14,201.58

Surveyor's name: Rasmi - 4p 90014068

Principal's name: ETHOZ Group Ltd

Survey Date & Time: 11/03/21 @ 1545