

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/MSG 21003237/49d3

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SMV 83376

at Workshop m/s

Intelex

of

Insured:

SL2744E

Policy No.

30004621471

Claims No.

254540

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

446

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

691C

Vehicle: IN / OUT

Date:

Person Contacted:

207131C.

Veh No:

SMV 83376

Yr Regn:

31/10/13

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW 316i

c.c

1598

Colour

Blue

A/C: Insured / Std / NI / NA

Sp. Reading

80100

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WBA3A12010J721447

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

235/35-R19

R:

255/30-R19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

11/3/21

D.O.I.

12/3/21

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

24th Feb

Account 30-10-2023

LTA # 35569 207131C

27/3/21 L/S # 4000 conf. and with Jeremy (Ref # 1546334, 792)

29/3/21 @ 11.11am revised to Ming Shao via Melissa.

Date/Time, File Pass to?

☐

: Preli. Report

1) 29/3/21

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

) S + RS. SI

) Photos

) Others

TOTAL

Report Format :

MER-TP

Lump Sum / I.B.I. (\$

4000

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$



NINETEEN
AUTOWERKS

NINETEEN AUTOWERKS PTE LTD

Blk 13 Kaki Bukit Road 4 #01-05
Bartley Biz Centre, Singapore 417807
Tel: (65) 9270 5882
nineteenautowerks@gmail.com

submit to insurance

not Authorised

Date : 11-Mar-21

Registration no. : SMV8337G / B.M.W. 316I 1.6 AT D/AB 4Dr ABS HID

DOA : Estimate No. : 19A047_SMV8337G_316I

12/3/21
2/55 4000
4 days

S/N	Qty	Item	Amount
-----	-----	------	--------

LIST ITEMS

1	1	Front bumper	1042.20	20/NE	1605.00	✓
2	2	Front bumper side retainer @ \$137.00		11	274.00	X
3	1	Front bumper support	182.20	CNE	360.60	✓
4	2	Front bumper grille @ \$378.60	107.70	0/5 CNE	757.20	12C
5	1	Front bumper tow cover	30.00	CNE	102.00	✓
6	2	Front bumper foglamp @ \$372.00	301.80	0/5 CNE	744.00	12C
7	2	Front bumper foglamp garnish @ \$121.00	86.60	0/5 TMI	242.00	12C
8	1	Front bumper centre grille		11	217.00	X
9	1	Front bumper inner sponge	54.85	70.11	326.00	✓
10	1	Front bumper reinforcement		11	614.00	X
11	2	Headlamp @ \$2644.00	2130.35	0/5 CNE	5288.00	12C
12	2	Headlamp HID ballast @ \$655.00		11	1310.00	X
13	2	Headlamp lower support @ \$182.00	132.15	0/5 CNE	364.00	12C
14	2	Front air guide @ \$ 126.90		11	253.80	X
15	1	Bonnet		11	1925.00	X
16	2	Bonnet inner lock @ \$282.00		11	564.00	X
17	1	Front fender RH		11	1044.20	X
18	1	Front fender inner shield RH		11	286.40	X

16277.20

P-4067.85
Less 5%
50
3864.45

813.86

15463.34

SPECIAL NETT ITEMS

1	1	front licence plate	CNE	60.00	40
2	1set	Front bumper clips	11	100.00	50
3	1set	Bonnet insulator clips	11	100.00	X
4	1	Bonnet sealant	11	100.00	X
5	2set	Front fender inner shield clips @ \$60.00	11	120.00	X

480.00

Parts Total

15943.34

Date : 11-Mar-21

Registration no. : SMV8337G / B.M.W. 316I 1.6 AT D/AB 4Dr ABS HID

DOA : Estimate No. : 19A047_SMV8337G_316I

S/N	Qty	Item	Amount
-----	-----	------	--------

LABOUR & MISC CHARGES

1	1	Panel beating and strenghten parts on accident area.	1500.00	500
2	1	Check wiring system after disconnect and connect.	80.00	20
3	1	R&R intercooler	11 180.00	X
4	1	R&R a/c condenser	11 180.00	X
5	1	R&R radiator	11 180.00	X
6	1	To apply undercoating for rust roofing.	11 200.00	X
7	1	Spray painting on accident area.	1200.00	550
Labour Total			3520.00	

Total Parts and Labour Cost of Repair			19463.34
--	--	--	-----------------

9 - 3864.45
 S/N - 90
 2 - 1070
 5024.45
 207
 4601.9

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: