

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AUTO & GENERAL INSURANCE (S) PTE LTD
190 CLEMENCEAU AVE #03-01
SINGAPORE SHOPPING CENTRE
SINGAPORE 239924

TEL: 6221 2199 FAX: 6725 0853
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 09/03/2021
TP Veh Reg No: SMG6726J

Estimate No: EST2100070

Date: 11 Mar 2021

Veh Reg No: **SMH6475C**

Make/Model: TOYOTA VIOS 1.5E
(AUTO)

Chasis No: MR2B23F3101162387

Reg. Date: 29/01/2019

Your Ref No: SMG6726J

Estimate Repair Cost to Vehicle No :SMH6475C

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
	List Price		
1	1 PC FRT DOOR RH	2,261.00	
2	1 PC FRT RH DOOR LOCK	577.10	
3	1 PC FRT DOOR GLASS REGULATOR ASSEMBLY RH	552.80	
4	1 PC FRT DOOR RUBBER RH	175.40	
5	1 PC FRT DOOR OUTER MOULDING RH	155.60	
6	1 PC FRT DOOR GLASS CHANNEL RH	124.70	
7	1 PC FRT DOOR FRAME BLACK DTICKER RH	45.20	
8	1 PC FRT DOOR TRIM RH	913.40	
9	1 PC FRT DOOR SIDE MIRROR RH	1,187.30	
10	1 PC FRT DOOR SIDE MIRROR COVER RH	98.50	
11	1 PC FRT FENDER RH	665.20	
12	1 PC FRT BUMPER	599.20	
13	1 PC FRT BUMPER SIDE RETAINER RH	34.40	
14	1 PC FRT FOG LAMP RH	289.20	
15	1 PC FRT FOG LAMP COVER RH	94.20	
16	1 PC HEADLAMP RH	1,248.90	
17	1 PC REAR DOOR RH	964.50	
18	1 PC REAR DOOR REGULATOR ASSY RH	552.20	
19	1 PC REAR DOOR OUTER MOULDING RH	144.30	
20	1 PC REAR DOOR GLASS CHANNEL RH	116.80	
21	1 PC REAR DOOR FRAME BLACK STICKER RH	40.20	
22	1 PC REAR DOOR LOCK RH	498.60	
23	1 PC REAR DOOR TRIM RH	733.20	
24	1 PC REAR DOOR RUBBER RH	172.50	
		12,244.40	
	Less 25%	3,061.10	9,183.34
	Special Net		
25	1 SET FRT BUMPER CLIPS	60.00	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AUTO & GENERAL INSURANCE (S) PTE LTD
190 CLEMENCEAU AVE #03-01
SINGAPORE SHOPPING CENTRE
SINGAPORE 239924

TEL: 6221 2199 FAX: 6725 0853
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 09/03/2021
TP Veh Reg No: SMG6726J

Estimate No: EST2100070

Date: 11 Mar 2021

Veh Reg No: **SMH6475C**

Make/Model: TOYOTA VIOS 1.5E
(AUTO)

Chasis No: MR2B23F3101162387

Reg. Date: 29/01/2019

Your Ref No: SMG6726J

Estimate Repair Cost to Vehicle No :SMH6475C

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
26	1 PC REAR SPORTS RIM RH	800.00	
		860.00	860.00
	Labour		
27	1 TO REMOVE AND REFIX FRT DOOR GLASS	100.00	
28	1 TO REMOVE AND REFIX REAR DOOR GLASS	100.00	
29	1 TO TRANSFER RH FRONT AND REAR DOOR POWER WINDOW WIRING	180.00	
30	1 TO REMOVE AND REFIT DOOR TRIM	80.00	
31	1 TO REMOVE AND REFIT DOOR QUARTER GLASS	80.00	
32	1 TO SPRAY UNDERSEAL	120.00	
33	1 (REAR) TO SPRAY PAINTING	1,600.00	
34	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,300.00	
35	1 TO CHECK WHEEL ALIGNMENT	120.00	
		3,680.00	3,680.00
		Total	S\$ 13,723.34
		Add GST @ 7%	960.63
		Total Amount Payable	<u>S\$ 14,683.97</u>

TOTAL: SINGAPORE DOLLAR FOURTEEN THOUSAND SIX HUNDRED EIGHTY THREE AND CENTS NINETY SEVEN ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd



AUTHORISED SIGNATURE