

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SMR1327C/2101008

11th March 2021

The Manager
Motor Claim Department
AIG Asia Pacific Insurance Pte Ltd
CHARTIS Building
78 Shenton Way #07-16
Singapore 079120

*Not Authorized
dealer
12/3/21
Excess \$?
Take 2nd. After repair
2 days.*

Date of Accident : 29th January 2021
Location : Lor 1 Toa Payoh
Name of Policyholder : Loh Khoo Hung
Policy No : 1900259720-01
Vehicle No : SMR 1327 C Mercedes GLA180

Estimated Supply of Parts & Labours

No.	Particulars	Qty	Price	Amounts
1	Front bumper fascia <i>DO/DE</i>	1	1,486.00	\$ 1,486.00
2	Front bumper clips <i>1 set</i>	1 set	70.00	\$ 70.00
3	Front bumper lower grille <i>one</i>	1	152.00	\$ 152.00
4	Front bumper lower grille garnish <i>n</i>	1	866.00	\$ 866.00
5	Front grille assy	1	1,557.00	\$ 1,557.00
				<u>\$ 4,131.00</u>

Labour Charges :-

Cut out, renew, knocking & welding front support panel, remove & install all damage parts & re-align body
Diagnostic & reset
Spray painting on damage parts
Check all lighting after repairs

Amounts

\$ 780.00 *380*
\$ 300.00 *X*
\$ 480.00 *380*
\$ 40.00 *20*

Labour Charge

Total Amount

GST will be reflected in the final bills.

\$ 1,600.00\$ 5,731.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: