



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS3/LPC20012257/Eqf3e2-1	Date: 25/03/2021
			Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGG 3158P	Veh. Inspected	SJN 716B	
Policy No.		Coverage (\$)	0.00	
Claim No.	19/20/20/VP05/023872	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	12/03/2021	
2. Vehicle Particulars & Condition				
Make & Model	HONDA FIT	c.c	1339	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	GE61150591	Colour	RED	
Odometer	186667 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/45 R16	MICHELIN	5 mm	
L/H Front Tyre	195/45 R16	MICHELIN	5 mm	
R/H Rear Tyre	195/45 R16	MICHELIN	5 mm	
L/H Rear Tyre	195/45 R16	MICHELIN	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	03/11/2020	Inspection Date	10/11/2020	
Survey held at	TOP 93 PTE LTD 51 UBI AVENUE 1, #01-05, PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	