



Like ceiling
Not Authorized
2/5 4100
12/3/21

NINETEEN AUTOWERKS PTE LTD

Blk 13 Kaki Bukit Road 4 #01-05
Bartley Biz Centre, Singapore 417807
Tel: (65) 9270 5882
nineteenautowerks@gmail.com

4 days.

Date : 10-Mar-21

Registration no. : SMV5892P / Honda Sream Sunroof 1.8L A

DOA : 10-Mar-21

Estimate No. : 19A046_SMV5892P_STREAM

S/N	Qty	Item	Amount
<u>LIST ITEMS</u>			
1	1	Tailgate	1270.00
2	1	Tailgate outer garnish	365.10
3	1	Tailgate logo	73.00
4	1	Tailgate emblem STREAM	89.00
5	1	Tailgate inner lock	258.00
6	1	Tailgate trimboard	466.70
7	2	Tailgate inner garnish side @ \$108.50	217.00
8	1	Tailgate inner garnish top	112.60
9	1	Tailgate weatherstrip	215.00
10	2	Tailgate hydraulic damper @ \$127.80	255.60
11	1	Tailgate windscreen	924.00
12	1	Tailgate windscreen moulding	118.00
13	2	Rear number plate lamp @ \$98.20	196.40
14	1	Rear wiper motor	399.60
15	1	Rear wiper arm	89.40
16	1	Rear wiper arm cover	72.00
17	2	Taillamp @ \$425.70	851.40
18	2	Taillamp lower bracket @ \$71.40	142.80
19	2	Taillamp seal @ \$30.00	60.00
20	1	Rear bumper	987.00
21	2	Rear bumper side retainer @ \$77.20	154.40
22	2	Rear bumper bracket @ \$54.30	108.60
23	1	Rear end panel	848.00
24	1	Rear end panel top garnish	207.80
25	1	Rear end panel top garnish cover	102.00
26	2	Rear fender inner garnish @ \$362.00	724.00
27	1	Exhaust pipe assy	970.90
28	3	Exhaust @ \$58.80	176.40

Less 20%

3842.4
202
3673.92



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

NINETEEN AUTOWERKS PTE LTD

Blk 13 Kaki Bukit Road 4 #01-05
Bartley Biz Centre, Singapore 417807
Tel: (65) 9270 5882
nineteenautowerks@gmail.com

Date : 10-Mar-21

Acknowledged by Repairer
Signature:
Date:

Registration no. : SMV5892P / Honda Sream Sunroof 1.8L A

DOA : 10-Mar-21

Estimate No. : 19A046_SMV5892P_STREAM

S/N	Qty	Item	Amount
-----	-----	------	--------

SPECIAL NETT ITEMS

1	1		
2	1set	Tailgate outer garnish clips	40.00
3	1set	Tailgate trimboard clips	50.00
4	2set	Tailgate inner garnish side clips @ \$35.00	70.00
5	1set	Tailgate inner garnish top clips	35.00
6	1	Tailgate windscreen primer and cleaner	100.00
7	1	Tailgate windscreen inner seal	80.00
8	1	Tailgate windscreen sealant	100.00
9	1	Tailgate windscreen tinted film	100.00
10	1	Tailgate sealant	220.00
11	1	Rear number plate	60.00
12	1	Rear wiper blade	80.00
13	2set	Taillamp clips @ \$30.00	60.00
14	1set	Rear bumper clips	80.00
15	1	Reverse camera	420.00
16	1set	Reverse sensor with module	300.00
17	1set	Rear end panel top garnish clips	40.00
18	1	Rear end panel sealant	100.00
19	2set	Rear fender inner garnish clips @ \$55.00	110.00
20	1	Exhaust chrome sleeve	150.00
			2255.00

Parts Total

LABOUR & MISC CHARGES

1	1	Panel beating and strenghten parts on accident area.	1600.00
2	1	Check wiring system after disconnect and connect.	80.00
3	1	R&R interior upholstery.	200.00
4	1	R&R tailgate component.	100.00
5	1	R&R tailgate windscreen.	180.00
6	1	R&R reverse sensor and check	100.00
7	1	R&R exhaust assy.	320.00
8	1	To apply undercoating for rust roofing.	200.00
9	1	Spray painting on accident area.	1500.00
			4280.00

Labour Total

Total Parts and Labour Cost of Repair