

Report Reference : **TP / 21022-01/AY / 2021**  
 Date of Report : **8 Mar 2021**

Ganshaam Ram Eednaani  
 Blk 8 Boon Keng Road  
 #23-146  
 Singapore 330008

**THIRD PARTY SURVEY**  
**ACCIDENT HAPPENED ON 19 Dec 2020**

Workshop Address : **M. W. Brothers Auto Repair**  
**No 2 Kaki Bukit Ave 2**  
**#02-02 Kaki Bukit AutoHub**  
**Singapore 417921**

As per your instruction dated **18 Jan 2021** with regard to the above matter. We have  
 carried out a physical inspection on the said vehicle **SJX 3166 R**. We enclosed herewith  
 our report and findings as follows:

**1. VEHICLE PARTICULARS**

Registration No	: SJX 3166 R	Engine No	: CDA053025
Model	: Audi A3	Mileage	: 94796
Year / Capacity	: 2010/1798	Colour	: Black
Chassis No	: TRUZZZ8P7A1004423		

**2. TYRES CONDITION**

	<u>Size</u>	<u>Made</u>	<u>Balance</u>		<u>Rim</u>
FRONT O/S :	225/45 R17	Michelin	4.00	mm	Sport
REAR O/S :	225/45 R17	Michelin	4.00	mm	Sport
FRONT N/S :	225/45 R17	Michelin	4.00	mm	Sport
REAR N/S :	225/45 R17	Michelin	4.00	mm	Sport

### 3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the front o/s portion(s). For more detail of the damages, please see photograph attached.

4. Estimated normal period of repair : 5 working days to complete.
5. Enclosed number of photograph : 48 copies.
6. In accordance to your instruction, we have Not Authorised repair to the vehicle and the survey was done on a "Without Prejudice" basis. We hope that this report will be of assistance to you in dealing with the matter.
7. Should you discover any discrepancy in the report, please kindly notify us within 2 weeks, or the report will be treated as correct.

#### Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle No: **SJX 3166 R**  
 Report No: **TP/ 21022-01/AY / 2021**

SPARE PARTS					
Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation	
<u>List Items</u>					
1	Front o/s wheel hub c/w bearing /	Necessary	\$ 285.00	\$ 285.00	/
1	Front o/s shock absorber X	Damage	\$ 865.00	\$ 865.00	X
1	Front o/s lower arm X	Damage	\$ 767.00	\$ 767.00	X
1	Front o/s knuckle arm X	Damage	\$ 812.50	\$ 812.50	X
1	Front o/s fender /	Damage	\$ 581.60	\$ 581.60	/
1	Front o/s fender inner shield /	Damage	\$ 222.30	\$ 222.30	/
1	Front o/s door X	Repair	\$ 1685.00	\$	
1	Front o/s door side mirror /	Damage	\$ 1560.00	\$ 1560.00	/
			\$ 6778.40	\$ 5093.40	2648.9
Discount 5.0%			\$ 338.92	\$ 254.67	
			\$ 6439.48	\$ 4838.73	2516.45
<u>Special Nett Items</u>					
1	Front o/s tyre (depreciation) X	Damage	\$ 500.00	\$ 200.00	X
1	Front o/s sport rim /	Damage	\$ 600.00	\$ 600.00	300
			\$ 1100.00	\$ 800.00	

**Spare Parts Total**      \$      7539.48      \$      5638.73

Vehicle No: **SJX 3166 R**  
 Report No: **TP/ 21022-01/AY / 2021**

**LABOUR COST**

S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
	Spare Parts Total c/f	\$ 7539.48	\$ 5638.73
1	To remove and refit damage parts, test for proper functioning and focus of headlamps.	\$ 50.00	\$ <del>40.00</del> X
2	To remove and refit front undercarriage.	\$ 200.00	\$ <del>150.00</del> 50
3	To check and re-adjust (Computerized) all wheel alignment.	\$ 100.00	\$ 60.00 ✓
4	To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools.	\$ 900.00	\$ <del>660.00</del> 400
5	To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.	\$ 900.00	\$ <del>660.00</del> 500
6	To apply undercoating on the repaired and replaced panels for rust protection.	\$ 100.00	\$ 30.00 ✓ 1040
<b>Total</b>		<u>\$ 9789.48</u>	<u>\$ 7238.73</u>

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of:

\$ **5800.00**

3856.45  
 20% = 3100  
 5 Days.

SDLS: FIVE THOUSAND EIGHT HUNDRED ONLY

  
 Qualified Appraiser