

Cheng Hoe Motor Pte Ltd

Bik 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

SMF 1696A
 TP/MSIG

M/S: MSIG INSURANCE (S) PTE LTD (SGX)

16 RAFFLES QUAY
 #24-01 HONG LEONG BUILDING
 SINGAPORE 048581

TEL: 68277660

FAX: 62257402

ATTN: Motor Claim Department

Estimate No: ES2190251/WS

Date: 22 Mar 2021

Policy No: DMPCSNW00145072000

Veh Reg No: SMF1696A

Make/Model: VOLKSWAGEN

VOLKSWAGEN
 TOURAN 1.4 TSI CL
 5T13NZ HLG

Chassis No: WVGZZZ1TZKW004592

Engine No: CZD175735

Reg. Date: 30/10/2018

WS Ref: TP/MSIG

Claim Type: Third Party

Accident Date: 10/03/2021

TP Veh Reg No: FBC7662D

Not Authorize

Henry Bepam

4 days

83380.26

Estimate Repair Cost to Vehicle No :SMF1696A

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 REAR BUMPER	1321.12	1 PC	1,355.70	✓
2 REAR BUMPER LOWER SKIRT	323.75	1 PC	495.10	✓
3 REAR BUMPER REINFORCEMENT		1 PC	623.20	✗
4 REAR BUMPER RH TAILLAMP		1 PC	430.00	✓
5 TAILGATE LOGO		1 PC	133.74	✓
6 TAILGATE EMBLEM (TAURAN)		1 PC	91.68	✓
			3,129.42	
		Less 10%	312.94	2,816.48
Special Net				
7 REVERSE SENSOR	200.00	1 PC	200.00	✓
			200.00	200.00
Labour				
8 REMOVE & REFIX REAR BUMPER ASSY, TAILLAMP, KNOCK & REPAIR TAILGATE, REAR RH FENDER & REALIGN THE SAME	500.00	1 LA	500.00	400
9 PUTTY & RESPRAY ON TAILGATE, REAR BUMPER, REAR RH FENDER	800.00	1 LA	800.00	660
10 REMOVE & REFIX REVERSE CAMERA & RESET SYSTEM	50.00	1 LA	50.00	✓
			1,350.00	1,350.00
			Total	SS 4,366.48
			Add GST @ 7%	305.65
			Total Amount Payable	SS 4,672.13

Parts \$2506.22
 Less 10% 250.62
 \$2255.60
 200
 1110
 \$3365.60

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE