

EFFICIENT MOTOR & ENGINEERING WORKS PTE LTD

56 LOYANG WAY # 06-07 ENTERPRISE BUILDING SINGAPORE 508775

VEHICLE NO : GBK3027Y

MAKE & MODEL : NISSAN / NV350 PANEL VAN 5DR 2.5 AT

CHASSIS NO : JN1MC2E26Z0031916

DATE : 12 MAR 2021

CLAIM TYPE : OD CLAIM

D.O.A : 06 MAR 2021

TO : INDIA INTERNATIONAL INSURANCE PTE LTD

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

S/No.	QTY	DESCRIPTION	CONDITION / REMARKS	COST PRICE	TOTAL PRICE
1	1	FRONT BUMPER / OR		\$ 280.00	\$ 280.00
2	1	FRONT BUMPER SIDE RETAINER LH / MIS		\$ 75.00	\$ 75.00
3	1	FRONT BUMPER TOWING COVER X NM		\$ 20.00	\$ 20.00
4	1	FRONT FOG LAMP GARNISH LH / MIS		\$ 65.00	\$ 65.00
5	1	FRONT BUMPER CENTRE BEAM X NM		\$ 95.00	\$ 95.00
6	1	FRONT BUMPER REINFORCEMENT X NM		\$ 350.00	\$ 350.00
7	1	FRONT BUMPER STAY LH X NM		\$ 50.00	\$ 50.00
8	1	CORNER PANEL LH / OR		\$ 195.00	\$ 195.00
9	1	FRONT GRILLE / OR		\$ 350.00	\$ 350.00
10	1	FRONT GRILLE EMBLEM / OR		\$ 50.00	\$ 50.00
11	1	HEADLAMP ASSY LH / OR		\$ 260.00	\$ 260.00
12	1	FRONT BUMPER CENTER GRILLE X NM		\$ 380.00	\$ 380.00
13	1	AIR GUIDE LOWER X NM		\$ 48.00	\$ 48.00
14	1	OIL COOLER / OR		\$ 580.00	\$ 580.00
15	1	OIL COOLER AIR GUIDE / OR		\$ 135.00	\$ 135.00
16	1	OIL COOLER LWR HOSE / NM		\$ 30.00	\$ 30.00
17	1	AIRCON LIQUID PIPE X NM		\$ 320.00	\$ 320.00
18	1	RADIATOR X NM		\$ 650.00	\$ 650.00
19	1	RADIATOR FAN BLADE X NM		\$ 250.00	\$ 250.00
20	1	RADIATOR FAN COWLING X NM		\$ 150.00	\$ 150.00
21	1	SIDE MIRROR LH X NM (glass) BR		\$ 340.00	\$ 60 340.00
22	1	STEP GARNISH LH / OR		\$ 95.00	\$ 95.00
23	1	FRT DOOR LH / OR		\$ 620.00	\$ 620.00
24	1	FRT DOOR HINGES LH X NM BT		\$ 40.00	\$ 40.00
25	1	FRT DOOR WEATHERSTRIP LH X NM CRU		\$ 70.00	\$ 70.00
				\$ 5,498.00	\$ 5,498.00

TOTAL PRICE	\$	5,498.00
PLUS 10%	\$	549.80
SUB TOTAL PRICE	\$	6,047.80

S/No.	QTY	DESCRIPTION	CONDITION / REMARKS	UNIT S/NETT	TOTAL S/NETT
1	1	FRONT BUMPER CLIPS SET / NM		\$ 50.00	\$ 30 50.00
2	1	FRONT GRILLE CLIPS SET / NM		\$ 50.00	\$ 20 50.00
3	1	FRONT DOOR CO.REG. STICKER / NM		\$ 25.00	\$ 25.00
4	1	FRONT NUMBER PLATE / NM		\$ 45.00	\$ 40 45.00
5	1	RADIATOR COOLANT X NM		\$ 50.00	\$ 50.00
6	1	TRANSMISSION FLUID / NM		\$ 80.00	\$ 80.00

TOTAL S/NETT	\$	300.00	\$	300.00
--------------	----	--------	----	--------

Labour Charges

	To cut/weld damaged panels, straighten & panel beat chassis frame & other panels, align doors, to remove & replace damaged parts.	\$ 1,200.00	600 700
	To Spray painting Front & LH/RH Side Portions.	\$ 1,200.00	600 800
	To remove & refit radiator, condenser & other components & top up A/C gas.	\$ 150.00	X
4	To check and rectify lighting, wiring and all electrical components.	\$ 150.00	30
5	To remove and transfer door components to new door	\$ 150.00	50
6	To remove & refit oil cooler & other components & top up transmission fluid.	\$ 150.00	50

TOTAL LABOUR

\$ 3,000.00

Total Cost of Repairs

\$ 9,347.80

(Total parts + Total S/Nett + Total Labour Cost)

Steve (LKK)

OD- 1/1 AL

Excess - ?

P/P

My Bel spm

6 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: