

Jongac Ins. Bhd
300 Beach Rd
#17-04/07 The Concourse
Singapore 189555.

Date: 11/3/21

Attn.: Motor Claims Department

Dear Sir/Madam

RE: Accident involving vehicles SMU 2886U & YN 1065L

On 11/3/21 at Shan Li Industrial Park,


It is in my opinion that the above mentioned accident was caused solely by the negligence of the driver of the vehicle no: YN 1065L

As the above vehicle was insured by your insurance company at the material time of the accident. I would appreciate that you could kindly arrange your surveyor to survey my vehicle soonest possible at the following address :-

Kan Fook Sing Motor Workshop
61 Defu Lane 12
Singapore 539147
Tel : 67479560 (O)

Thank you

Yours faithfully

A large, stylized handwritten signature in black ink, consisting of a large loop and a trailing flourish.



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquater: 61 Defu Lane 12 Singapore 539147

Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428

E-mail: ryan@kanfs.net/ patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883

Tel: (65) 6481 5150 Fax: (65) 6481 8683

LONPAC INSURANCE BHD

DATE : 11-03-2021

300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE
199555

VEHICLE NO. : SMU2856U

ACCIDENT DATE : 11-03-2021 08:20

THIRD PARTY REF. : YN1065L

ATTN: MOTOR CLAIMS DEPT.

ESTIMATE COST OF REPAIR TO VEICLE SMU2856U LEXUS ES250 4DR SEDAN (AUTO) EXECUTI

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	1	FRONT BONNET	800.00
2	1	FRONT BONNET HINGE RH	55.00
3	1	FRONT FENDER RH	350.00
4	1	FRONT FENDER SHIELD RH	150.00
5	10	FRONT FENDER SHIELD CLIP@\$1.50	15.00
6	1	FRONT FENDER TOP GARNISH RH	190.00
7	1	FRONT HEADLAMP RH	1200.00
8	1	FRONT GRILLE CHROME RH	85.00
9	1	FRONT BUMPER	330.00
10	1	FRONT BUMPER SIDE RETAINER RH	24.00
11	1	FRONT BUMPER TOGLAMP COVER RH	95.00
12	1	FRONT BUMPER FOGLAMP COVER CHROME RH	75.00
13	1	FRONT BUMPER TOW COVER RH	25.00
			3,394.00
ADD 20 %			678.80
TOTAL (A)			4,072.80

LABOUR CHARGES

1	1	TO CHECK WIRING SYSTEM	30.00
2	1	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FI- TTING NEW PARTS	650.00
3	1	SPRAYPAINTING CHARGES	720.00



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquater: 61 Defu Lane 12 Singapore 539147

Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428

E-mail: ryan@kanfs.net/ patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883

Tel: (65) 6481 5150 Fax: (65) 6481 8683

VEHICLE NO. : SMU2856U
ACCIDENT DATE : 11-03-2021 08:20
THIRD PARTY REF. : YN1065L

QTY PARTS DESCRIPTION

AMOUNT (SG\$)

TOTAL (D)

1,400.00

ESTIMATE TOTAL

5,472.80