



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquater: 61 Defu Lane 12 Singapore 539147
Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428
E-mail: ryan@kanfs.net/ patricia@kanfs.net
Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883
Tel: (65) 6481 5150 Fax: (65) 6481 8683

LONPAC INSURANCE BHD

DATE : 11-03-2021

300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555

VEHICLE NO. : SMU2856U

ACCIDENT DATE : 11-03-2021 08:20

THIRD PARTY REF. : YN1065L

ATTN: MOTOR CLAIMS DEPT.

ESTIMATE COST OF REPAIR TO VEHICLE SMU2856U LEXUS ES250 4DR SEDAN (AUTO) EXECUTI

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	1	FRONT BONNET / <i>BMC</i>	• 800.00 ✓
2	1	FRONT BONNET HINGE RH X ✓ BR	• 55.00 ✓
3	1	FRONT FENDER RH / <i>BMC</i>	• 350.00 ✓
4	1	FRONT FENDER SHIELD RH / <i>at</i>	• 150.00 ✓
5	10	FRONT FENDER SHIELD CLIP@\$1.50 / <i>rec</i>	• 15.00 ✓
6	1	FRONT FENDER TOP GARNISH RH cut X NN	190.00 X
7	1	FRONT HEADLAMP RH / <i>at</i>	• 1200.00 ✓
8	1	FRONT GRILLE CHROME RH at X NN	• 85.00 X
9	1	FRONT BUMPER / <i>re</i>	• 320 330 .00 ✓
10	1	FRONT BUMPER SIDE RETAINER RH / <i>at</i>	• 24.00 ✓
11	1	FRONT BUMPER TOGLAMP COVER RH / <i>at</i>	• 95.00 ✓
12	1	FRONT BUMPER FOGLAMP COVER CHROME RH cut X NN	75.00 X
13	1	FRONT BUMPER TOW COVER RH X NN	25.00 X
			3,394.00 3009
ADD 20 %			678.80
TOTAL (A)			4,072.80 3610.8

LABOUR CHARGES

1	1	TO CHECK WIRING SYSTEM	30.00 ✓
2	1	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	650.00 400
3	1	SPRAYPAINTING CHARGES	720.00 400



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquater: 61 Defu Lane 12 Singapore 539147

Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428

E-mail: ryan@kanfs.net/ patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883

Tel: (65) 6481 5150 Fax: (65) 6481 8683

VEHICLE NO. : SMU2856U
ACCIDENT DATE : 11-03-2021 08:20
THIRD PARTY REF. : YN1065L

QTY PARTS DESCRIPTION

AMOUNT (SG\$)

TOTAL (D)

1,400.00 830

ESTIMATE TOTAL

5,472.80

5394.8

6mo Qianp - 8288 0282.

4 Days.

12/3/2021

P/P

resal print photos

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: 61 Defu Lane 12 Singapore S39147

Tel: (65) 6747 9560, 6743 5344 Fax: (65) 6748 1006, 6281 8428

Branch: 1 Kaki Bukit Avenue 6 #01-13 Singapore 417883

Tel: (65) 6481 5150 Fax: (65) 6481 8683

E-mail: ryan@kanfs.net/ patricia@kanfs.net

LONPAC INSURANCE BHD

300 BEACH ROAD

#17-04/07 THE CONCOURSE

SINGAPORE 199555

DATE: 16-04-2021

VEHICLE NO. : SMU2856U
ACCIDENT DATE : 11-03-2021 08:20
THIRD PARTY REF. : YN1065L

ATTN: MOTOR CLAIMS DEPT.

SUPPLEMENTARY COST OF REPAIR TO VEHICLE SMU2856U LEXUS ES250 4DR SEDAN (AUTO)

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	10	FRONT BUMPER CLIP @ \$1.50 ✓ NEC	15.00 ✓
2	1	FRONT BUMPER SENSOR ✓ DM	130.00 ✓
3	1	FRONT BUMPER INNER FOAM ✓ CRA	45.00 ✓
4	1	FRONT GRILLE ✓ CRA	550.00 ✓
5	1	FRONT GFENDER TOP PROTECTOR RH ✓ CRA	55.00 ✓
			795.00
ADD 20%			159.00
TOTAL (A)			954.00 ✓
SUPPLEMENTARY TOTAL			954.00