

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/GRB21003281/KBS3Q2
Date: 17/05/2021

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SCY2188L	Insured Vehicle No :	SLK4122E
Date of Loss:	07/03/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0000967

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SCY2188L	Engine No:	074036
Make & Model:	PORSCHE MACAN, 2.0 A/T ABS D/AIRBAG AWD (A)	Chassis No:	WP1ZZZ95ZFLB08823
Reg. Date:	28/11/2014 (Man. Year: 2014)	Odometer:	82850 km
Colour:	Metallic Grey		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	235/60 R18	Rear Tyre Size:	255/55 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 8 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,513.70	0.00	2,513.70	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,020.00	800.00	220.00	21.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,533.70	800.00	2,733.70	77.36
+ GST 7.00/7.00% (S\$)	247.36	56.00	191.36	77.36

Nett Amount (S\$)	3,781.06	856.00	2,925.06	77.36
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	12/03/2021		
Date Inspected:	18/03/2021	Inspected At:	Kum Chew Motor Workshop (160 Sin Ming) (HQ) 160 Sin Ming Drive, #05-08 Sin Ming Autocity Singapore 575722
Estimated Period of Repair:	3.0 days		

Adjuster:	KENNETH KONG	Manager:	CHUA ZHEN LI
------------------	--------------	-----------------	--------------

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 May 2021)
Parts:	M1-SUV	PORSCHE MACAN 2.0 A/T ABS D/AIRBAG AWD (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SCY2188L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	1,232.00 FL	*- FL
2	1		*REAR BUMPER RETAINER	Serviceable	91.00 FL	*- FL
3	1		*REAR SPORT RIM -L/H	Repair	1,470.00 FL	*- FL
						F=Franchise part. L=ListItemDisc.
					Sub Total (\$)	2,793.00
					- List Item Discount on L Items 10.00/10.00% (\$)	279.30
					Total Parts (\$)	2,513.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PULL ,KNOCK ON ACCIDENT PORTION & CHARGE ABOVE PART	New	380.00	250.00
2	TO SPRAY & PAINT ON REAR ACCIDENT PORTION	New	580.00	550.00
3	TO ANTI-RUST REAR AFFECTED AREAS	New	60.00	0.00
Gross Labour Cost (\$\$)			1,020.00	800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >