


N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

EZY-1 LEASING PTE LTD
 15 YISHUN INDUSTRIAL ST 1 #01-21
 SINGAPORE 768091

Contact : 68730308 91040309

TP AXA
 Jasper

ESTIMATE

Repair Code : CLM16732

Date in : 12/03/2021

Vehicle Num. : SJV6577D

Model : TOYOTA VIOS E AUTO

Chassis/Eng# : MR053HY9305148875/1NZY032691

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
AIR CLEANER BOX <i>could</i>	1	1084.90	1084.90 <i>A77</i>
FRONT BUMPER <i>Distorted</i>	1	495.00	✓ 495.00
FRONT BUMPER 'LOGO' EMBLEM <i>me</i>	1	55.00	✓ 55.00
FRONT BUMPER INNER GARNISH <i>could</i>	1	115.00	✓ 115.00
FRONT BUMPER LH FOGLAMP COVER <i>del'd</i>	1	71.00	✓ 71.00
FRONT BUMPER LH LOWER AIR GUIDE <i>could</i>	1	65.80	✓ 65.80
FRONT BUMPER LH REINFORCEMENT BRACKET <i>Best</i>	1	250.00	✓ 250.00
FRONT BUMPER LH UNDER COVER <i>form</i>	1	161.90	✓ 161.90
FRONT BUMPER LH UPPER AIR GUIDE <i>me</i>	1	48.50	+ 48.50
FRONT BUMPER REINFORCEMENT <i>Distorted</i>	1	399.50	✓ 399.50
FRONT BUMPER SIDE RETAINER L/R <i>RH LH Dist</i>	2	85.00	170.00 <i>85</i>
FRONT GRILLE <i>me</i>	1	276.40	+ 276.40
FRONT LH AIRBAG IMPACT SENSOR <i>me</i>	1	374.60	+ 374.60
FRONT LH FENDER <i>Distorted</i>	1	637.70	637.70 <i>A25</i>
FRONT LH FENDER 'VVTI' EMBLEM <i>me</i>	1	19.30	✓ 19.30
FRONT LH FENDER BRACKET <i>me</i>	1	46.60	+ 46.60
FRONT LH FENDER INNER SHIELD <i>form</i>	1	175.60	✓ 175.60
FRONT LH HEADLAMP <i>could</i>	1	525.00	✓ 525.00

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

EZY-1 LEASING PTE LTD
 15 YISHUN INDUSTRIAL ST 1 #01-21
 SINGAPORE 768091

Contact : 68730308 91040309

ESTIMATE

Repair Code : CLM16732

Date in : 12/03/2021

Vehicle Num. : SJV6577D

Model : TOYOTA VIOS E AUTO

Chassis/Eng# : MR053HY9305148875/1NZY032691

FRONT LH HEADLAMP TOP BRACKET <i>Ne</i>	3320.10	1	95.60	+	95.60
FRONT SUPPORT PANEL <i>Regr</i>		1	925.00	+	925.00
FRONT SUPPORT PANEL LH BRACKET <i>Regr</i>	2490.07	1	68.00	+	68.00
Subtotal before discount					6,060.40
Percentage discount 25%					1,515.10
Sub-total 1					4,545.30
FRONT BUMPER CLIPS - SET <i>Ne</i>		1	50.00	30	50.00
FRONT LH FENDER INNER SHIELD CLIPS - SET <i>Ne</i>	60	1	50.00	30	50.00
RADIATOR COOLANT <i>Ne</i>		1	50.00	+	50.00
Subtotal before discount					150.00
Percentage discount 0%					0.00
Sub-total 2					150.00
Parts-total					4,695.30

LABOUR

To remove, reinstall air con parts, vacuums, refill air con gas. (to FR) + 120.00

To remove, reinstall electrical wiring harness, check lighting. (to FR) ~~30.00~~

To reset system after repair works ~~120~~ ~~280.00~~

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident. ~~650~~ ~~950.00~~

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident. ~~600~~ ~~900.00~~

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

EZY-1 LEASING PTE LTD
15 YISHUN INDUSTRIAL ST 1 #01-21
SINGAPORE 768091

Contact : 68730308 91040309

ESTIMATE

Repair Code : CLM16732
Date in : 12/03/2021
Vehicle Num. : SJV6577D
Model : TOYOTA VIOS E AUTO
Chassis/Eng# : MR053HY9305148875/1NZY032691

To apply anti-rust chemical on repaired and replaced panel.

	60	80.00
Labour Total	1460	2,390.00
Parts & Labour Total		7,085.30

*** This is a computer-generated document which requires no signature.***

page 3

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian L
H/s 12/03/21.
0 Days.

total: 34010.07

H/s: 3.2K

3.2K