

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

China - CP/PJ
LKK -

Date: 10.03.2021

Time: 15:04:30

Page: 1

TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305457970
 REGN NO : SHC3584B
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G2)
 DATE OF REGN : 10.07.2019
 DATE/TIME IN : 10.03.2021 10:15
 ACCIDENT DATE : 09.03.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0104-2282-G	REAR BUMPER	1	459.40	20.00	367.52	Ry
0002	04-01-0104-2533-G	REAR BUMPER CTR MOULDING	1	451.25	20.00	361.00	de ✓
0003	04-01-0104-2545-G	REAR BUMPER LWR MOULDING	1	155.00	20.00	124.00	Ry
0004	04-01-0104-2288-G	REAR BUMPER BEAM	1	394.80	20.00	315.84	?
0005	04-01-0104-3819-G	REAR BUMPER STAY LH	1	138.10	20.00	110.48	?
0006	04-01-0104-3919-G	REAR BUMPER STAY RH	1	138.10	20.00	110.48	?
0007	04-01-0104-2370-G	REAR BUMPER FOGLAMP	1	201.50	20.00	161.20	cut ✓
0008	04-01-0101-0111-G	REAR BUMPER CLIPS	10 L	22.00	20.00	17.60	✓
0009	09-01-9999-0068-A	REVERSE SENSOR	1	180.00		180.00	rw ✓
0010	04-01-0104-1150-A	REAR BUMPER MAT	1	50.00		50.00	x
0011	FNPS	REAR NO.PLATE W/TRIM COVER	1 N	55.00		55.00	ans ✓

SUB-TOTAL : 1,853.12

JOB NATURE

COMFORTDELGRO ENGINEERING PTE LTD

Date: 10.03.2021

REPAIR ESTIMATE

Time: 15:04:30

Page: 2

China - CP/P
LKK -

p IS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305457970
 REGN NO : SHC3584B
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G2)
 DATE OF REGN : 10.07.2019
 DATE/TIME IN : 10.03.2021 10:1
 ACCIDENT DATE : 09.03.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0000 PB	PANEL BEATING	400.00	350
0001 SP	SPRAYPAINT CHARGE	300.00	250
0002 L	R/I REVERSE SENSOR	120.00	30

SUB-TOTAL : 820.00

TOTAL : 2,673.12

Lmfs
 MVA NAME & SIGNATURE
 DATE :

AUTHORISED : YES / NO
 SURVEYOR NAME & SIGNATURE
 DATE :

Tanpin 97495749
wp' 10/3/21 @ 5pm
2 days
r/p Resurvey after wpn'
tanpin @ lkk auto

Wspkln

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 10.03.2021 14:30

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order:

JC NO.: 305457970


OMER	REGN NO.: SHC3584B	MILEAGE
IS COMFORT TRANSPORTATION PTE LTD	MAKE : HYUNDAI	FUEL E.....1/2.....F
OMER NO. 7010045	MODEL IONIQ(G2)	DATE/TIME IN 10.03.2021 10:15
LESS 383 SIN MING DRIVE	YR OF MANU. 10.07.2019	TARGET DATE
Singapore SINGAPORE 575717	CHASSIS CODE KMHC851CVKU164609	COMPLETION DATE/TIME
(R) 65508755 (O)		
(P)		
JUNT CARD NO.		

JOB DESCRIPTION

Accident Date: 09.03.2021

NATURE: 3P 09.03.2021

S/NO LABOR CODE DESCRIPTION



KED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

No.: **SHC3584B** **LIMITS**

Vehicle No.: **SHC3584B**

Service Advisor

Signature/Date

Name of Service Advisor

Date

turned to Service Reception upon collection

To be kept by Security Guard