

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Douglas Ong Chu Chong

Date: 01 Oct 2021

Preliminary Advice

Insured Vehicle No	: SJA68G	Accident Date	: 25/01/2021
TP Vehicle No	: FBN5299A	Assignment Date	: 12/03/2021
Make	: HONDA FS150F	Est. Duration of Repair	: 6
Date of Inspection	: 15/03/2021		
Inspection At	: SG 98 MOTOR PTE LTD (HQ) BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 SINGAPORE 569622		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,580.50
Revised Amount	:S\$	3,852.50
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,852.50
 Lump Sum Repair	 :S\$	 3,050.00

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	8,000.00
COE / PARF Rebate	:S\$	2,793.00
Salvage Value	:S\$	
Margin for Repair	:S\$	5,207.00

Remarks

- () The vehicle is economical for repair
 () The vehicle is not economical for repair
 () Part-by-Part repair
 (X) Lump Sum repair

- (X) The above survey was conducted on a 'without prejudice' basis.

Please note that the preliminary advise amount (Revised) stated are subject to consistency check, part prices and labour cost .