

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : TAN YONG LI JUSTIN
994B BUANGKOK LINK
#15-337
SINGAPORE 532994

ATTN:

Your Ref No: SMP2460D
Claim Type: Third Party → AIG
Accident Date: 10/03/2021
TP Veh Reg No: GBF6472B

Estimate No: MC1901815
Date: 11 Mar 2021
Policy No: V0110711
Veh Reg No: SMP2460D
Make/Model: NISSAN SYLPHY 1.6
CVT

Not Authored

1 - 2 day

Estimate Repair Cost to Vehicle No :SMP2460D

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
SPARE PARTS			
1 REAR BOOT LOCK	1 PC	115.00	X
2 REAR BOOT LOCK SENSOR	1 PC	95.00	X
3 REAR BOOT RUBBER	1 PC	112.00	X
4 REAR BUMPER	1 PC	679.00	?
5 REAR BUMPER SIDE RETAINER LH & RH	2 PC	84.00	X
6 REAR BUMPER CLIPS	12 PC	61.20	?
7 REAR BUMPER SPONGE CTR	1 PC	55.00	X
8 REAR BUMPER SPONGE LH & RH	2 PC	201.60	X
9 REAR BUMPER STAY LH & RH	2 PC	136.00	X
		1,538.80	
	Less 10%	153.88	1,384.92
Special Nett			
10 REVERSE SENSOR	1 SET	200.00	X
		200.00	200.00
LABOUR			
11 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	60.00	?
12 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD.TO KNOCK & REPAIR REAR END APENL INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	500.00	1200
13 TO SPRAY REAR BUMPER,REAR END PANEL.	1 PC	500.00	2000
		1,060.00	1,060.00



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: