

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/III21003301/UGS3Q2
Date: 05/10/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D20MFL0000326_01		
Claimant Vehicle No :	SDW3033S	Insured Vehicle No :	SMC1503P		
Date of Loss:	11/03/2021	Nature of Claim:	TP	Claim No:	MFL2021D0001112

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDW3033S		
Make & Model:	MERCEDES-BENZ E200K, 1.8 (A)	Engine No:	27195630887472
Reg. Date:	12/03/2008 (Man. Year: 2007)	Chassis No:	WDB2110412B141214
Colour:	Black	Odometer:	231573 km
Engine Capacity:	1796 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	245/45 R18	Rear Tyre Size:	245/45 R18
Front Left Side:	Continental 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,034.73	1,616.02	4,418.71	73.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,640.00	890.00	750.00	45.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,674.73	2,506.02	5,168.71	67.35
Approved Total (Overridden) (S\$)		2,000.00		

Nett Amount (S\$)	7,674.73	2,000.00	5,674.73	73.94
+ Loss of Use (2.0 x S\$80.00/day) (S\$)		160.00		
(S\$)		2,160.00		
Liabe Amount (50.00%) (S\$)		1,080.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,087.45		

INSPECTION

Date of Assignment: 12/03/2021

Date Inspected: 12/03/2021

Estimated Period of Repair: 2.0 days

Inspected At:

Choo Motor Spray Painter (HQ)
 1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki Bukit
 Singapore 417883

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Sep 2021)
Parts:	143	MERCEDES-BENZ E200K 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDW3033S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR O/S	Repair	1,850.21 F	*- FL
2	1		*FRONT DOOR GLASS OUTER MOULDING O/S	Not Necessary	288.20 F	*- FL
3	1		*FRONT DOOR MIRROR ASSY O/S }	Cracked / Damaged	1,655.61 F	*1,125.58 FL
4	1		*FRONT DOOR MIRROR MOTOR O/S }		1,200.50 F	*- FL
5	1		*FRONT DOOR MIRROR OUTER COVER O/S	Cracked	185.00 F	*185.00 FL
6	1		*FRONT DOOR MIRROR GLASS O/S	Cracked	855.21 F	*485.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	6,034.73	1,795.58
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	179.56
Total Parts (\$)	6,034.73	1,616.02

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REFIX FRT DOOR INNER TRIM BOARD	New	80.00	50.00
3	TO SPRAY RUST PROOFING	New	50.00	0.00
4	TO RESET & REPROGRAMME SYSTEM	New	380.00	0.00
5	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	500.00	320.00
6	TO PUTTY & SPRAY PAINTING	New	580.00	500.00
Gross Labour Cost (S\$)			1,640.00	890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >