

see ceilla

Not Authorized
Hak

17/3/21
2/5 \$ 2000/
2 days.

CHOO MOTOR SPRAY PAINTER
1 KAKI BUKIT AVE 6 #01-39 AUTOBAY
SPORE 417883

VEHICLE No: SDW 3033S

1PC	FRONT DOOR O/S	n	\$1,850.21	X
1PC	FRONT DOOR GLASS OUTER MOULDING O/S	11	\$288.20	X
1PC	FRONT DOOR MIRROR ASSY O/S	one/Damaged.	1125.58	\$1,655.61
1PC	FRONT DOOR MIRROR OUTER COVER O/S	one	192	\$185.00
1PC	FRONT DOOR MIRROR GLASS O/S	one	485.00	\$855.21
1PC	FRONT DOOR MIRROR MOTOR O/S	complete	(102)	\$1,200.50 X
				\$6,034.73

TO CHECK WIRING
TO DISMANTLE & REFIX FRT DOOR INNER TRIM BOARD
TO SPRAY RUST PROOFING
TO RESET & REPROGRAMME SYSTEM
LABOUR FOR PANEL BEATING & REPLACED PARTS
TO PUTTY & SPRAY PAINTING

\$50.00	20
\$80.00	50
11	\$50.00 X
11	\$380.00 X
	\$500.00 320
	\$580.00 500
TOTAL	\$7,674.73

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

p 1795.58
102
p-1616.02
L-830
2506.02
2024.