

J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578,
Defu Industrial Park C, Singapore 539186
Tel : 6343-0934 Fax : 6343-0921
Email : jmartauto@gmail.com
Registration No: 201400246D
GST Reg. No: 201400246D

10-Mar-21

Our ref : TP/4959/21

Wong Keng Chuan Terrence

TPALG.
Justin

JM6CW1071G0122943

RE : estimate cost for vehicle no : SMU 8857C

1 pc	tailgate	Buckled	\$	1,771.10	1637
1 pc	logo emblem			99.00	
1 pc	Mazda emblem			60.20	
1 pc	5 emblem			84.40	
1 pc	Skyactiv emblem			110.60	
1 pc	tailgate lock	new		233.00	+
1 pc	tailgate w/strip	new	3450.20	259.60	x
1 pc	rear bumper	Delud	2760.16	1,050.00	961
2 pcs	rear bumper retainer	new		164.00	
8 pcs	rear bumper clips	new		40.00	
1 pc	rear bumper reinforcement	Bent.		463.10	294.
1 pc	end panel	Regr		656.00	+
				4,991.00	
			less 20%	998.20	
				3,992.80	
1 pc	rear w/screen gum	new	250	50.00	snett
1 pc	reverse sensor	Repl		250.00	200
	Panel beating.			800.00	400
	Spray painting.			800.00	400
	Transfer tailgate fitting.		1000	80.00	
	Remove & refit rear w/screen.			120.00	
				6092.80	
			Plus 7% GST	426.50	
				6519.30	

SD : Six thousand five hundred nineteen & cents thirty only.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj
H/S 11/03/21

04 Days

total: 401016

H/S: 32K