

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *SMH 8727M*
at Workshop m/s *JMK*

of _____

Insured: *SMG 6903P*

Policy No. _____

Claims No. *CM102100800/RUC*

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: *451k.*

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: *7* days Res.: Yes or NoLum Sum: *20* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Date / Time Action / Instruction *207 Hk.*
LTA 841268 sys. 4hrs.
net 9732

27/3/21 1/5 @ 4900 Confirmed with Shimin Ured 8 1928.64, 287.7
28/3/21 @ 11.37am revised to Ruth Chua by email.

Veh No: *SMH 8727M* Yr Regn: *13/7/16*Type: *M.Car* / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or *CA/*Make: *Nissan Sylphy* C.C. *1598*Colour: *Ref* A/C: Insured / Std / NI / NASp. Reading: *74370* T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: *MNTBBAB1720027422*Gen. Cond: *Good* / Fair / Poor / BurntSteering: *In order* / Jammed / Leaked / Burnt orBrake: *In order* / Jammed / Leaked / Burnt orModi: *Nil* / S/Rim / STD A/Rim orTyre Size: F: *205/53-R16*
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or *Continental*Front *6* mm Rear *6* mmR/Bal. *6* mm L/Bal. *6* mmD.O.A. *11/3/21* D.O.I. *15/3/21*

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear
 The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Preli. Report

1) *29/3/21*☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: *7*Resurvey No. of Trip: *2*

Survey Fee:

Transportation:

Report Format :

Lump Sum / I.B.I. (\$) *TP 4900*Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

) S + RS, SI

) Photos

) Others

TOTAL

REPAIR ESTIMATE

ATTN: MOTOR CLAIMS DEPARTMENT
OWNER: Woon Soo Huat
INSURER: NTUC INCOME INSURANCE CO-OPERATIVE Ltd
DOA: 11/03/2021

Est No. : EST21030109
Date : 13-Mar-21
Vehicle Num : SMH8727M
Make/Model : Nissan Sylphy
Chassis # : MNTBBAB17Z0027422
Engine # : HR16990277B
Yr. Of Manu : 2016

No.	Description	Qty	U/P	Amt
Section: LIST ITEMS				
1	Bootlid <i>But/But</i> <i>1190.60</i>	1.00	1263.80	1263.80
2	Bootlid Chrome <i>11</i>	1.00	295.70	295.70 X
3	Bootlid Lamp RH/LH <i>See</i>	1.00	241.60	241.60 X
4	Bootlid "Logo" Emblem <i>See</i> <i>45.80</i>	1.00	69.70	69.70
5	Bootlid "Hinge" Emblem <i>Sylphy</i> <i>See</i> <i>75.20</i>	1.00	98.50	98.50
6	Bootlid Hinge RH/LH <i>See</i>	2.00	78.40	156.80 X
7	Bootlid Inner Lock <i>But</i>	1.00	89.60	89.60
8	Bootlid Inner Lock Latch <i>11</i>	1.00	69.70	69.70 X
9	Bootlid Rubber <i>7w1</i>	1.00	95.30	95.30
10	Bootlid Insulator <i>11</i>	1.00	238.80	238.80 X
11	Rear End Panel <i>Bad 500</i> <i>454.30</i>	1.00	538.40	538.40
12	Rear End Panel Top Garnish <i>7w1</i> <i>85.00</i>	1.00	107.10	107.10
13	Rear End Panel Sponge <i>7w1</i>	3.00	95.10	285.30 <i>245</i>
14	Spare Tyre Board <i>negot</i> <i>210.90</i>	1.00	521.20	521.20
15	Spare Tyre Panel <i>R</i>	1.00	843.80	843.80 X
16	Spare Tyre Sponge <i>See</i> <i>262.30</i>	1.00	279.40	279.40
17	Taillamp RH/LH <i>11</i>	2.00	471.90	943.80 X
18	Rear Bumper <i>See</i> <i>607.00</i>	1.00	707.00	707.00
19	Rear Bumper Reflector RH/LH <i>O/S m.s</i> <i>45.50</i>	2.00	75.00	150.00 <i>120</i>
20	Rear Bumper Sensor RH/LH <i>shard S/N</i>	2.00	380.00	760.00 <i>200</i>
21	Rear Bumper Retainer RH/LH <i>O/S But</i> <i>20.50</i>	2.00	45.60	91.20 <i>100</i>
22	Rear Bumper Damper Bracket RH/LH <i>O/S 20</i>	2.00	59.30	118.60 <i>120</i>
23	Rear Bumper Clips <i>See</i> <i>30.00</i>	10.00	5.50	55.00
24	Antenna Sensor <i>See</i>	1.00	84.40	84.40
25	Rear RH Fender <i>But</i> <i>1419.20</i>	1.00	1487.40	1487.40

Continue on next page...

REPAIR ESTIMATE

ATTN: MOTOR CLAIMS DEPARTMENT
 OWNER: Woon Soo Huat
 INSURER: NTUC INCOME INSURANCE CO-OPERATIVE Ltd
 DOA: 11/03/2021

Est No. : EST21030109
 Date : 13-Mar-21
 Vehicle Num : SMH8727M
 Make/Model : Nissan Sylphy
 Chassis # : MNTBBAB17Z0027422
 Engine # : HR16990277B
 Yr. Of Manu : 2016

No.	Description	Qty	U/P	Amt
-----	-------------	-----	-----	-----

Section: LIST ITEMS

26	Petrol Tank Cover 17	1.00	86.70	86.70 X
27	Petrol Tank Cover Lock 17	1.00	76.40	76.40 X

Amt S\$ 9755.20

Discount (30.00%) S\$ 2926.56

Subtotal S\$ 6828.64

Section: SPECIAL NETT ITEMS

28	Number Plate With Cover SLL	1.00	50.00	50.00 X
----	-----------------------------	------	-------	---------

Amt S\$ 50.00

Discount (0.00%) S\$ 0.00

Subtotal S\$ 50.00

Section: LABOUR

29	To Panel Beat and Renewal Of All Necessary Damaged Parts	1.00	1400.00	1400.00 1200
30	To Sand Down, Putty and Spray Paint on Necessary Damaged	1.00	1250.00	1250.00 1100
31	To Check All Wiring	1.00	50.00	50.00 30
32	To Align Headlamp	1.00	50.00	50.00 12 X
19	To Dismantle & Reinstall Rear Windscreen To Facilitate Repair	1.00	180.00	180.00 120
24	To Remove and Refit RH Door Quater Glass	1.00	100.00	100.00 50

Amt S\$ 3030.00

Discount (0.00%) S\$ 0.00

Subtotal S\$ 3030.00 2500

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LIST ITEMS Subtotal S\$ 6828.64 2500.00

SPECIAL NETT ITEMS Subtotal S\$ 50.00

LABOUR Subtotal S\$ 3030.00 6175.57

Total S\$ 9908.64 200 4540.

Joo Hak Kee Auto Pte. Ltd.