



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

### General Details

Involving TPVD TOYOTA LEXUS IS250 EXECUTIVE A/T (SMF1246R)

Date of Loss 23 November 2020

Time of Loss 18.40

Loss Description GBE5549B (INSD) C/W SMF1246R (TP)

Comment

### Workshop Details

Total Rebate Amount

0

Nett Loss Amount

\$71,000.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (TP)

Days of work completion \*

20



SERVICE REQUESTS

MESSAGES

CLAIMS



# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

## Vehicle & Driver Details

Vehicle Registration#	SMF1246R	Purchase Date	<input type="text" value="dd/mm/yyyy"/>
Registration State	<input type="text" value="SINGAPORE"/>	Registration Date *	<input type="text" value="26/03/2015"/>
Mileage	<input type="text" value="70538"/>	Age of Vehicle	5

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Manufacturing Year		<input type="text" value="2015"/>
Make	TPVD TOYOTA	<input type="text" value="TOYOTA"/>
LEVEL IS 250		<input type="text"/>

### Driver Details

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Driver Name	FOO SEY HIIANG	<input type="text"/>
Date of Birth	12 August 1970	<input type="text" value="dd/mm/yyyy"/>

Model CATEGORY	LEXUS IS250 POLICY EXECUTIVE A/T INFORMATION	LEXUS IS250 EXECI INFORMATION
Type		<div>▼</div>
Type of Paint		
Chassis No		JTHBF5D29050681
Engine No		4GR1038711
Engine Capacity		2500
Sum Insured		0
Market Value		71000

CATEGORY Age	FNOL INFORMATION 50	POST SURVEY INFORMATION
Occupation	Unknown	
Education Qualification	Other	<div>▼</div>
Driving Experience	0	
Driver License #		
License Type		<div>▼</div>
License Issue Date		<div>dd/mm/yyyy</div> <div></div>
License Expiration Date		<div>dd/mm/yyyy</div> <div></div>

CATEGORY	FNOL INFORMATION	POST SURVEY
Address	SG, Singapore	<input type="text"/>
Address type	Personal Correspondence	<input type="text" value="▼"/>
Gender	Male	<input type="text" value="▼"/>
Marital status	Unknown	<input type="text" value="▼"/>
Identification #	S7027430B	<input type="text"/>



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

### Detailed Assessment

Inspection Date \*

17/03/2021



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/  
Unnamed Driver  
Excess

0

### Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake  
(Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Other Excess

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

Rear Tyre Size

Front left side

Rear left side

Front right side

Rear right side



SERVICE REQUESTS

MESSAGES

CLAIMS



# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

## Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%	<input type="text"/>	Salvage%	<input type="text"/>
Discount%	<input type="text" value="10"/>	Settlement%	<input type="text" value="100"/>

## Paint Labour/Material Ratio

Paint Labour Ratio	<input type="text" value="20"/>	Paint Material Ratio	<input type="text" value="80"/>
--------------------	---------------------------------	----------------------	---------------------------------

Cash Loss

YesNo

Part Supplied by AXA

YesNo

Save







SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details   Vehicle & Driver Details   Vehicle Condition   Taxes & Ratio   Parts & Labour   Miscellaneous   Summary

Parts













Add












Approve












Deny









Submit All

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
<input type="checkbox"/>		0	1		BOOT LID	Replaced	0	892.1	No		10			802.89	Reviewing
<input type="checkbox"/>		0	1		BOOT LID LOGO	Replaced	0	90	No		10			81	Reviewing
<input type="checkbox"/>		0	1		BOOT LID 'LEXUS' EMBLEM	Replaced	0	80	No		10			72	Reviewing
<input type="checkbox"/>		0	1		BOOT LID 'IS250' EMBLEM	Replaced	0	70	No		10			63	Reviewing
<input type="checkbox"/>		0	1		BOOT LID O/S LAMP	Replaced	0	320	No		10			288	Reviewing
<input type="checkbox"/>		0	1		BOOT LID N/S LAMP	Replaced	0	320	No		10			288	Reviewing
<input type="checkbox"/>		0	2		REAR LICENCE PLATE LAMP	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		BOOT LID OPENING SWITCH	Replaced	0	281.65	No		10			253.49	Reviewing

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
<input type="checkbox"/>		0	1		BOOT LID INNER TRIM	Replaced	0	567.93	No		10			511.14	Reviewing
<input type="checkbox"/>		0	10		BOOT LID INNER TRIM CLIP	Replaced	0	5.5	No		10			49.5	Reviewing
<input type="checkbox"/>		0	1		BOOT LID INNER LOCK	Replaced	0	473.7	No		10			426.33	Reviewing
<input type="checkbox"/>		0	1		BOOT LID LOCK STRIKER	Replaced	0	110.65	No		10			99.59	Reviewing
<input type="checkbox"/>		0	1		BOOT LID WEATHERSTRIP	Replaced	0	190	No		10			171	Reviewing
<input type="checkbox"/>		0	2		BOOT LID HINGE	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	2		BOOT LID HINGE COVER	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	4		BOOT LID STOPPER	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		REAR BUMPER	Replaced	0	936.6	No		10			842.94	Reviewing
<input type="checkbox"/>		0	1		REAR BUMPER DIFFUSER	Replaced	0	489.5	No		10			440.55	Reviewing
<input type="checkbox"/>		0	1		REAR BUMPER TOW COVER	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	2		REAR BUMPER REFLECTOR	Serviceable	0	0	No		10			0	Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
<input type="checkbox"/>		0	2		REAR BUMPER PDC SENSOR (4PCS)	Replaced	0	236.15	No		10			425.07	Reviewing
<input type="checkbox"/>		0	1		SET REAR BUMPER PDC SENSOR WIRE HARNESS	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		REAR BUMPER SPONGE	Replaced	0	190	No		10			171	Reviewing
<input type="checkbox"/>		0	1		REAR BUMPER REINFORCEMENT	Replaced	0	580	No		10			522	Reviewing
<input type="checkbox"/>		0	2		REAR BUMPER SIDE RETAINER	Replaced	0	82.5	No		10			148.5	Reviewing
<input type="checkbox"/>		0	1		REAR END PANEL	Replaced	0	830	No		10			747	Reviewing
<input type="checkbox"/>		0	1		REAR END PANEL GARNISH	Replaced	0	395.66	No		10			356.09	Reviewing
<input type="checkbox"/>		0	1		REAR N/S EXHAUST SILENCER	Repair	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		REAR O/S EXHAUST SILENCER	Repair	0	0	No		10			0	Deny
<input type="checkbox"/>		0	2		REAR EXHAUST CHROME PIPE	Replaced	0	230	No		10			414	Reviewing
<input type="checkbox"/>		0	6		REAR EXHAUST MOUNTING	Serviceable	0	0	No		10			0	Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
<input type="checkbox"/>		0	1		REAR O/S EXHAUST INSULATOR	Repair	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		REAR N/S EXHAUST INSULATOR	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		REAR FLOOR BOARD	Replaced	0	422	No		10			379.8	Reviewing
<input type="checkbox"/>		0	1		REAR FLOOR PANEL	Repair	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		REAR FLOOR PANEL UNDER COVER	Replaced	0	310.6	No		10			279.54	Reviewing
<input type="checkbox"/>		0	1		REAR N/S FENDER	Repair	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		REAR FENDER INNER TRIM N/S	Replaced	0	412	No		10			370.8	Reviewing
<input type="checkbox"/>		0	1		REAR FENDER INNER TRIM O/S	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	5		REAR FENDER INNER TRIM CLIP O/S	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	5		REAR FENDER INNER TRIM CLIP N/S	Replaced	0	5.5	No		10			24.75	Reviewing
<input type="checkbox"/>		0	1		SPARE TYRE RETAINER LOCK	Serviceable	0	0	No		10			0	Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
<input type="checkbox"/>		0	1		REAR TOOL BOARD	Replaced	0	189.9	No		10			170.91	Reviewing
<input type="checkbox"/>		0	1		REAR SMART KEYLESS ANTENNA	Replaced	0	241.3	No		10			217.17	Reviewing
<input type="checkbox"/>		0	2		TAILLAMP	Replaced	0	380	No		10			684	Reviewing
<input type="checkbox"/>		0	2		TAILLAMP SIDE COVER	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	2		TAILLAMP PANEL	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		REAR WINDSCREEN MOULDING	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		REAR LICENCE PLATE GARNISH	Replaced	0	248.83	No		10			223.95	Reviewing
<input type="checkbox"/>		0	1		BOOT LID OUTER KEY CYLINDER LOCK	Serviceable	0	0	No		10			0	Deny


Labour







Add




Approve

Deny

Submit All

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT
<input type="checkbox"/>		0		TOWING CHARGES	0	0	0	0	Deny	

EDIT		SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT
<input type="checkbox"/>		0		TO DISCONNECT AND CHECK REAR ELECTRICAL WIRING, HARNESS, WIRE SOCKETS, ETC. TO REMOVE AND REINSTALL DAMAGED PARTS, TEST AND RECTIFY FOR PROPER FUNCTIONING	0	30	0	0	Reviewing	
<input type="checkbox"/>		0		TO REMOVE AND REFIX INNER TRIMS, GARNISHES, LININGS AND UPHOLSTERY TO FACILITATE REPAIRS	0	60	0	0	Reviewing	
<input type="checkbox"/>		0		TO REMOVE AND REPLACE REAR BUMPER SENSOR AND REVERSE CAMERA	0	50	0	0	Reviewing	
<input type="checkbox"/>		0		TO REMOVE AND REPLACE REAR EXHAUST PIPE SYSTEM TO FACILITATE REPAIRS	0	60	0	0	Reviewing	
<input type="checkbox"/>		0		TO REMOVE AND REFIX REAR WINDSCREEN GLASS TO FACILITATE REPAIRS AND PERFORM WATER TEST	0	0	0	0	Deny	
<input type="checkbox"/>		0		TO REMOVE AND REPLACE REAR DAMAGED PARTS AS LISTED ABOVE INCLUDING REINSTATEMENT OF THE NECESSARY ATTACHMENTS AND FITTINGS TO FACILITATE REPAIRS. JACK UP, STRAIGHTEN, }	0	1000	0	0	Reviewing	

EDIT		SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT
<input type="checkbox"/>		0		PANEL BEAT AND RESHAPE THE AFFECTED PARTS AND COMPONENTS. TO CORRECT AND REALIGN THE NECESSARY PARTS }	0	0	0	0	Reviewing	
<input type="checkbox"/>		0		TO APPLY RUSTPROOFING, RESEAL TUFF-COATING TREATMENT TO REAR REPLACED / REPAIRED PARTS AND PANELS	0	60	0	0	Reviewing	
<input type="checkbox"/>		0		TO PUTTY AND SPRAY PAINTING ON REAR DAMAGED PORTION INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS	0	1000	0	0	Reviewing	



SERVICE REQUESTS

MESSAGES

CLAIMS



# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add





Approve

Deny

Submit All

	EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>		0	DAYS OF REPAIR : 7 DAYS	Reviewing		0		
<input type="checkbox"/>		0	1 SET REAR BUMPER CLIP	Reviewing		35	REPLACED	
<input type="checkbox"/>		0	1 SET REAR LICENCE PLATE WITH HOLDER	Reviewing		50	REPLACED	
<input type="checkbox"/>		0	REVERSE	Deny		0	SERVICEABLE	



EDIT		SR NO	CAMERA NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT REMOVE
<input type="checkbox"/>		0	1 SET REAR WINDSCREEN SEALANT	Deny		0	SERVICEABLE 
<input type="checkbox"/>		0	2 SETS TAILLAMP CLIP	Reviewing		25	NECESSARY 



SERVICE REQUESTS

MESSAGES

CLAIMS



# Assessment Details

General & Workshop Details		Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
Estimated Claim Amount	\$0.00			Adjusted Claim Amount	\$11,894.01		
CATEGORY	ESTIMATE	ADJUSTED					
Spare Parts	\$0.00	\$9,524.01					
Labour	\$0.00	\$2,260.00					
Miscellaneous	\$0.00	\$110.00					

Submit for Review



SERVICE REQUESTS

MESSAGES

CLAIMS



# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>		0	FINAL LUMP SUM	Reviewing	9500		

Submit for Review